

PIC16F87X

PIC16F87X Rev. B Silicon Errata Sheet

The PIC16F87X (Rev. B) parts you have received conform functionally to the Device Data Sheet (DS30292A), except for the anomalies described below.

All the problems listed here will be addressed in future revisions of the PIC16F87X silicon.

All devices have been marked revision "B" and "engineering sample" or "ES".

1. Module: Program Memory

When instruction execution resumes after an internal program cycle terminates, the following 16 memory locations must be blank (all 1's). Otherwise this may cause unexpected device operation.

Work Around

To address this issue, use the following software sequence. Fixed in silicon revision B3.

EXAMPLE 1: CODE WORK AROUND

```
bsf
                    STATUS, RP1
bcf
                    STATUS, RPO
bcf
                    INTCON, GIE
                                    ; If interrupts enabled
movlw 0x55
movwf
                    EECON2
movlw
                    0xAA
movwf
                    EECON2
bsf
                    EECON1, WR
nop
; When used with MPASM, the data 0x3fff places all '1's at that point in the program.
; This executes as an addlw Oxff instruction which is completely benign at this point
; in the program.
           0 \times 3 f f f
                                     ; Instruction with all ones
data
           0x3fff
                                     ; needed to clear high voltage
data
data
           0x3fff
                                      ; out of the program memory
data
           0x3fff
                                      ; arrays
data
           0x3fff
           0x3fff
data
data
           0x3fff
           0x3fff
data
data
           0x3fff
data
           0x3fff
           0x3fff
data
           0x3fff
data
           0x3fff
data
data
           0x3fff
data
           0x3fff
           0x3fff
data
           0x3fff
data
bsf
                    INTCON, GIE
                                             ; If interrupts enabled
bcf
                    EECON1, WREN
```

PIC16F87X

2. Module: MSSP - SPI mode

The SDI pin is controlled by the module and not by the state of the TRIS bit. This means that the SDI pin cannot be an output when the MSSP module is in SPI mode.

Work Around

None for current silicon revision (fixed in silicon revision B4)

3. Module: Electrical Specifications

The Supply Voltage specification has not yet met the design target (Data Sheet specification). The specification for these devices is shown in Table 1.

4. Module: A/D Specifications

The Offset Error specification has not yet met the design target (Data Sheet specification). The specification for these devices is shown in Table 1.

5. Module: TMR1

When operating in external clock mode (TMR1CS is set), reading either of the timer 1 registers (TMR1H or TMR1L) may cause the timer not to increment as expected. This occurs for both synchronous and asynchronous inputs.

The scenarios which display this are:

- a) When a read operation of the TMR1H register occurs, the TMR1L register may not increment
- b) When a read operation of the TMR1L register occurs, the TMR1H register may not increment. This improper operation is only an issue when the TMR1L register increments from FFh to 00h (FFh \rightarrow 00H) during the read of the TMR1L register.

Work Around

Do not read either the TMR1H or the TMR1L registers when operating in external clock mode (TMR1CS is set). If the application needs to read the 16-bit counter, evaluate if this function can be moved to the TMR0 or one of the other timer resources on the device.

TABLE 1: DC SPECIFICATION CHANGES FROM DATA SHEET

| Param No. | Sym. | Characteristic | Tested | cation | Data Sheet Specification | | | Units | |
|--------------|------|----------------|--------|--------|-----------------------------|-----|-----|-------|-----|
| | | | Min | Тур | Max | Min | Тур | Max | |
| D001 | Vdd | Supply Voltage | 2.5 | _ | 5.5 | 2.0 | _ | 5.5 | V |
| A06 | Eoff | Offset Error | _ | _ | < ± 2 | _ | _ | < ± 1 | LSb |

6. Module: I/O Ports

The IOL condition for the VOL specification has been relaxed for the I/O ports. Table 2 shows what the current data sheet specification is, as well as the limit that the device is currently tested to.

Work Around

None

Clarifications/Corrections to the Data Sheet:

In the Device Data Sheet (DS30292A), the following clarifications and corrections should be noted:

None.

TABLE 2: DC SPECIFICATION CHANGES FROM DATA SHEET

| Param No. | Sym. | Characteristic | Tested Specification | | | Data Sheet Specification | | | | Units | |
|--------------|------|------------------------------------|----------------------|-----|-----|---|-----|-----|-----|--|---|
| | | | Min | Тур | Max | Condition | Min | Тур | Max | Condition | |
| D080 | Vol | Output Low Voltage I/O ports | | _ | 0.6 | IOL = 3.0 mA VDD = 4.5 V -40°C -to 85°C | _ | _ | 0.6 | IOL = 8.5 mA VDD = 4.5 V -40°C -to 85°C | V |
| D080A | | | _ | _ | 0.6 | IOL = TBD mA VDD = 4.5 V -40°C -to 125°C | _ | _ | 0.6 | IOL = 7.0 mA VDD = 4.5 V -40°C -to 125°C | V |

Note the following details of the code protection feature on PICmicro® MCUs.

- The PICmicro family meets the specifications contained in the Microchip Data Sheet.
- Microchip believes that its family of PICmicro microcontrollers is one of the most secure products of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the PICmicro microcontroller in a manner outside the operating specifications contained in the data sheet. The person doing so may be engaged in theft of intellectual property.
- · Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable".
- Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our product.

If you have any further questions about this matter, please contact the local sales office nearest to you.

Information contained in this publication regarding device applications and the like is intended through suggestion only and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. No representation or warranty is given and no liability is assumed by Microchip Technology Incorporated with respect to the accuracy or use of such information, or infringement of patents or other intellectual property rights arising from such use or otherwise. Use of Microchip's products as critical components in life support systems is not authorized except with express written approval by Microchip. No licenses are conveyed, implicitly or otherwise, under any intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, FilterLab, KEELOQ, microID, MPLAB, PIC, PICmicro, PICMASTER, PICSTART, PRO MATE, SEEVAL and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

dsPIC, ECONOMONITOR, FanSense, FlexROM, fuzzyLAB, In-Circuit Serial Programming, ICSP, ICEPIC, microPort, Migratable Memory, MPASM, MPLIB, MPLINK, MPSIM, MXDEV, PICC, PICDEM, PICDEM.net, rfPIC, Select Mode and Total Endurance are trademarks of Microchip Technology Incorporated in the U.S.A.

Serialized Quick Turn Programming (SQTP) is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2002, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.





Microchip received QS-9000 quality system certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona in July 1999. The Company's quality system processes and procedures are QS-9000 compliant for its PICmicro® 8-bit MCUs, KEELO© code hopping devices, Serial EEPROMs and microperipheral products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001 certified.



WORLDWIDE SALES AND SERVICE

AMERICAS

Corporate Office

2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Fax: 480-792-7277 Technical Support: 480-792-7627 Web Address: http://www.microchip.com

Rocky Mountain

2355 West Chandler Blvd. Chandler, AZ 85224-6199
Tel: 480-792-7966 Fax: 480-792-7456

Atlanta

500 Sugar Mill Road, Suite 200B Atlanta, GA 30350
Tel: 770-640-0034 Fax: 770-640-0307

Boston

2 Lan Drive, Suite 120 Westford, MA 01886 Tel: 978-692-3848 Fax: 978-692-3821

Chicago

333 Pierce Road, Suite 180 Itasca, IL 60143

Tel: 630-285-0071 Fax: 630-285-0075

Dallas

4570 Westgrove Drive, Suite 160 Addison, TX 75001 Tel: 972-818-7423 Fax: 972-818-2924

Detroit

Tri-Atria Office Building 32255 Northwestern Highway, Suite 190 Farmington Hills, MI 48334 Tel: 248-538-2250 Fax: 248-538-2260

Kokomo

2767 S. Albright Road Kokomo, Indiana 46902 Tel: 765-864-8360 Fax: 765-864-8387

Los Angeles

18201 Von Karman, Suite 1090 Irvine, CA 92612

Tel: 949-263-1888 Fax: 949-263-1338

New York

150 Motor Parkway, Suite 202 Hauppauge, NY 11788 Tel: 631-273-5305 Fax: 631-273-5335

San Jose

Microchip Technology Inc. 2107 North First Street, Suite 590 San Jose, CA 95131 Tel: 408-436-7950 Fax: 408-436-7955

Toronto

6285 Northam Drive, Suite 108 Mississauga, Ontario L4V 1X5, Canada Tel: 905-673-0699 Fax: 905-673-6509

ASIA/PACIFIC

Australia

Microchip Technology Australia Pty Ltd Suite 22, 41 Rawson Street Epping 2121, NSW Australia

Tel: 61-2-9868-6733 Fax: 61-2-9868-6755

China - Beijing

Microchip Technology Consulting (Shanghai) Co., Ltd., Beijing Liaison Office Unit 915 Bei Hai Wan Tai Bldg.

No. 6 Chaoyangmen Beidajie Beijing, 100027, No. China Tel: 86-10-85282100 Fax: 86-10-85282104

China - Chengdu

Microchip Technology Consulting (Shanghai)
Co., Ltd., Chengdu Liaison Office
Rm. 2401, 24th Floor, Ming Xing Financial Tower No. 88 TIDU Street Chengdu 610016, China

Tel: 86-28-6766200 Fax: 86-28-6766599

China - Fuzhou

Microchip Technology Consulting (Shanghai) Co., Ltd., Fuzhou Liaison Office Unit 28F, World Trade Plaza No. 71 Wusi Road Fuzhou 350001, China Tel: 86-591-7503506 Fax: 86-591-7503521

China - Shanghai

Microchip Technology Consulting (Shanghai) Co., Ltd. Room 701, Bldg. B

Far East International Plaza No. 317 Xian Xia Road Shanghai, 200051

Tel: 86-21-6275-5700 Fax: 86-21-6275-5060

China - Shenzhen

Microchip Technology Consulting (Shanghai) Co., Ltd., Shenzhen Liaison Office Rm. 1315, 13/F, Shenzhen Kerry Centre, Renminnan Lu Shenzhen 518001, China Tel: 86-755-2350361 Fax: 86-755-2366086

Hong Kong

Microchip Technology Hongkong Ltd. Unit 901-6, Tower 2, Metroplaza 223 Hing Fong Road Kwai Fong, N.T., Hong Kong Tel: 852-2401-1200 Fax: 852-2401-3431

India

Microchip Technology Inc. India Liaison Office Divvasree Chambers 1 Floor, Wing A (A3/A4) No. 11, O'Shaugnessey Road Bangalore, 560 025, India Tel: 91-80-2290061 Fax: 91-80-2290062

Japan

Microchip Technology Japan K.K. Benex S-1 6F 3-18-20, Shinyokohama Kohoku-Ku, Yokohama-shi Kanagawa, 222-0033, Japan Tel: 81-45-471- 6166 Fax: 81-45-471-6122

Korea

Microchip Technology Korea 168-1, Youngbo Bldg. 3 Floor Samsung-Dong, Kangnam-Ku Seoul, Korea 135-882

Tel: 82-2-554-7200 Fax: 82-2-558-5934

Singapore

Microchip Technology Singapore Pte Ltd. 200 Middle Road #07-02 Prime Centre Singapore, 188980

Tel: 65-334-8870 Fax: 65-334-8850

Taiwan

Microchip Technology Taiwan 11F-3, No. 207 Tung Hua North Road Taipei, 105, Taiwan

Tel: 886-2-2717-7175 Fax: 886-2-2545-0139

EUROPE

Denmark

Microchip Technology Nordic ApS Regus Business Centre Lautrup hoj 1-3 Ballerup DK-2750 Denmark Tel: 45 4420 9895 Fax: 45 4420 9910

France

Microchip Technology SARL Parc d'Activite du Moulin de Massy 43 Rue du Saule Trapu Batiment A - Ier Etage 91300 Massy, France Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79

Germany Microchip Technology GmbH Gustav-Heinemann Ring 125 D-81739 Munich, Germany Tel: 49-89-627-144 0 Fax: 49-89-627-144-44

Italy

Microchip Technology SRL Centro Direzionale Colleoni Palazzo Taurus 1 V. Le Colleoni 1 20041 Agrate Brianza Milan, Italy Tel: 39-039-65791-1 Fax: 39-039-6899883

United Kingdom

Arizona Microchip Technology Ltd. 505 Eskdale Road Winnersh Triangle Wokingham Berkshire, England RG41 5TU

Tel: 44 118 921 5869 Fax: 44-118 921-5820

01/18/02