



Intel® 80219 General Purpose PCI Processor

Specification Update

July 2004

Notice: The Intel® 80219 General Purpose PCI Processor (80219) may contain design defects or errors known as errata that may cause the product to deviate from published specifications. Current characterized errata are documented in this specification update.

Document Number: **274020-002**



INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL® PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER, AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

Intel products are not intended for use in medical, life saving, life sustaining applications.

Intel may make changes to specifications and product descriptions at any time, without notice.

Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined." Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them.

Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined." Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them.

The Intel® 80219 General Purpose PCI Processor may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copies of documents which have an ordering number and are referenced in this document, or other Intel literature may be obtained by calling 1-800-548-4725 or by visiting Intel's website at <http://www.intel.com>.

Copyright© Intel Corporation, 2004

AlertVIEW, i960, AnyPoint, AppChoice, BoardWatch, BunnyPeople, CablePort, Celeron, Chips, Commerce Cart, CT Connect, CT Media, Dialogic, DM3, EtherExpress, ETOX, FlashFile, GatherRound, i386, i486, iCat, iCOMP, Insight960, InstantIP, Intel, Intel logo, Intel386, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Intel ChatPad, Intel Create&Share, Intel Dot.Station, Intel GigaBlade, Intel InBusiness, Intel Inside, Intel Inside logo, Intel NetBurst, Intel NetStructure, Intel Play, Intel Play logo, Intel Pocket Concert, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel TeamStation, Intel WebOutfitter, Intel Xeon, Intel XScale, Itanium, JobAnalyst, LANDesk, LanRover, MCS, MMX, MMX logo, NetPort, NetportExpress, Optimizer logo, OverDrive, Paragon, PC Dads, PC Parents, Pentium, Pentium II Xeon, Pentium III Xeon, Performance at Your Command, ProShare, RemoteExpress, Screamlane, Shiva, SmartDie, Solutions960, Sound Mark, StorageExpress, The Computer Inside, The Journey Inside, This Way In, TokenExpress, Trillium, Vivonic, and VTune are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

The ARM* and ARM Powered logo marks (the ARM marks) are trademarks of ARM, Ltd., and Intel uses these marks under license from ARM, Ltd.

*Other names and brands may be claimed as the property of others.

Contents

Revision History	5
Preface.....	6
Summary Table of Changes.....	7
Identification Information.....	11
Core Errata	13
Non-Core Errata.....	20
Specification Changes	24
Specification Clarifications	26
Documentation Changes	29



This Page Left Intentionally Blank



Revision History

Date	Version	Description
July 2004	002	Added Specification Clarification 7.
November 2003	001	Initial Release.

Preface

This document is an update to the specifications contained in the Affected Documents/Related Documents table below. This document is a compilation of device and documentation errata, specification clarifications and changes. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools.

Information types defined in Nomenclature are consolidated into the specification update and are no longer published in other documents.

This document may also contain information that was not previously published.

Affected Documents/Related Documents

Title	Order
<i>Intel® 80219 General Purpose PCI Processor Developer's Manual</i>	274017
<i>Intel® 80219 General Purpose PCI Processor Advance Information Datasheet</i>	274018
<i>Intel® 80219 General Purpose PCI Processor Design Guide</i>	274019

Nomenclature

Errata are design defects or errors. These may cause the [Intel® 80219 General Purpose PCI Processor¹](#) behavior to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present on all devices.

Specification Changes are modifications to the current published specifications. These changes will be incorporated in any new release of the specification.

Specification Clarifications describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in any new release of the specification.

Documentation Changes include typos, errors, or omissions from the current published specifications. These will be incorporated in any new release of the specification.

Note: Errata remain in the specification update throughout the product life cycle, or until a particular stepping is no longer commercially available. Under these circumstances, errata removed from the specification update are archived and available upon request. Specification changes, specification clarifications and documentation changes are removed from the specification update when the appropriate changes are made to the appropriate product specification or user documentation (datasheets, manuals, etc.).

1. ARM* architecture compliant.

Summary Table of Changes

The following table indicates the errata, specification changes, specification clarifications, or documentation changes which apply to the Intel® 80219 General Purpose PCI Processor product. Intel may fix some of the errata in a future stepping of the component, and account for the other outstanding issues through documentation or specification changes as noted. This table uses the following notations:

Codes Used in Summary Table

Stepping

X:	Errata exists in the stepping indicated. Specification Change or Clarification that applies to this stepping.
(No mark)	
or (Blank box):	This erratum is fixed in listed stepping or specification change does not apply to listed stepping.

Page

(Page):	Page location of item in this document.
---------	---

Status

Doc:	Document change or update will be implemented.
PlanFix:	This erratum may be fixed in a future stepping of the product.
Fixed:	This erratum has been previously fixed.
NoFix:	There are no plans to fix this erratum.

Row

	Change bar to left of table row indicates this erratum is either new or modified from the previous version of the document.
--	---



Core Errata

No.	Steppings	Page	Status	Errata
	A-0			
1	X	13	NoFix	Boundary Scan Is Not Fully Compliant to the IEEE 1149.1 Specification
2	X	13	NoFix	Drain Is Not Flushed Correctly when Stalled in the Pipeline
3	X	14	NoFix	Undefined Data Processing-'like' Instructions are Interpreted as an MSR Instruction
4	X	14	NoFix	Debug Unit Synchronization with the TXRXCTRL Register
5	X	14	NoFix	Extra Circuitry Is Not JTAG Boundary Scan Compliant
6	X	15	NoFix	Incorrect Decode of Unindexed Mode, Using Addressing Mode 5, Can Corrupt Protected Registers
7	X	15	NoFix	Load Immediately Following a DMM Flush Entry is Also Flushed
8	X	15	NoFix	Trace Buffer Does Not Operate Below 1.3 V
9	X	15	NoFix	Data Cache Unit Can Stall for a Single Cycle
10	X	16	NoFix	Aborted Store that Hits the Data Cache May Mark Writeback Data As Dirty
11	X	17	NoFix	Performance Monitor Unit Event 0x1 Can Be Incremented Erroneously by Unrelated Events
12	X	17	NoFix	In Special Debug State, Back-to-Back Memory Operations Where the First Instruction Aborts May Cause a Hang
13	X	18	NoFix	Accesses to the CP15 ID register with opcode2 > 0b001 returns unpredictable values
14	X	18	NoFix	Disabling and re-enabling the MMU can hang the core or cause it to execute the wrong code
15	X	19	NoFix	Updating the JTAG parallel register requires an extra TCK rising edge

Non-Core Errata

No.	Steppings	Page	Status	Errata
	A-0			
1	X	20	NoFix	The ATU Returns Invalid Data for the DWORD that Target Aborted from the MCU when Using 32-Bit Memory, ECC Enabled and in PCI Mode
2	X	20	NoFix	PBI Issue When Using 16-bit PBI Transactions in PCI Mode
3	X	21	NoFix	MCU Pointers are Incorrect following a Restoration from a Power Fail
4	X	21	NoFix	PMU Does Not Account for when the Arbiter Deasserts GNT# One Cycle before FRAME#
5	X	21	NoFix	Lost Data During Bursts of Large Number of Partials with 32-bit ECC Memory
6	X	22	NoFix	The MTTR1 (Core Multi-Transaction Timer) is not operating due to improper behavior of the core internal bus request signal (REQ#)
7	X	22	NoFix	The MCU supports a page size of 2 Kbytes for 64-bit mode
8	X	23	NoFix	Vih Minimum Input High Voltage (Vih) level for the PCI pins

Specification Changes

No.	Steppings	Page	Specification Changes
	A-0		
1	X	24	Signal NC2 was renamed to P_BMI (AE23). New function added to signal P_BMI.

Specification Clarifications

No.	Steppings	Page	Status	Specification Clarifications
	A-0			
1	X	26	NoFix	The Intel® 80219 general purpose PCI processor is compliant with the PCI Local Bus Specification, Revision 2.2 but it is not compliant with PCI Local Bus Specification, Revision 2.3
2	X	26	NoFix	Modifications to the Hot-Debug procedure are necessary for the Intel® 80219 general purpose PCI processor when flat memory mapping is not used (Virtual Address = Physical Address)
3	X	27	Doc	BAR0 Configuration When Using the Messaging Unit (MU)
4	X	27	Doc	Reading Unpopulated SDRAM Memory Banks
5	X	27	Doc	32-bit Writes-to-Unaligned 64-bit Addresses, are Promoted to 64-bit Aligned Writes
6	X	28	Doc	In-order Delivery not guaranteed for data blocks described by a single DMA descriptor
7	X	28	Doc	Writing to reserved registers can cause unexpected behavior


Documentation Changes

No.	Document Revision	Page	Status	Documentation Changes
				None for this revision of this specification update.

Identification Information

Markings

Figure 1. Topside Markings





Die Details

Stepping	Part Number	QDF (Q)/ Specification Number (SL)	Voltage (V)	Intel® 80219 General Purpose PCI Processor Speed (MHz)	Notes
A-0	FW80219M400	Q690	3.3	400	Samples
A-0	FW80219M600	Q691	3.3	600	Samples
A-0	FW80219M400	SL7CL	3.3	400	Production Material
A-0	FW80219M600	SL7CM	3.3	600	Production Material

Device ID Registers

Device and Stepping	Processor Device ID (CP15, Register0 - opcode_2=0)	ATU Device ID (ATUDID)	ATU Revision ID (ATURID)	JTAG Device ID
A-0 (400 MHz)	0x69052E20	0x031A	0x00	0x0927E013
A-0 (600 MHz)	0x69052E30	0x031B	0x00	0x0927F013

Core Errata

1. Boundary Scan Is Not Fully Compliant to the IEEE 1149.1 Specification

Problem: The IEEE Standard 1149.1 specifies the boundary scan logic to support two main goals:

1. To allow the interconnections between the various components to be tested, test data can be shifted into all the boundary-scan register cells associated with component output pins and loaded in parallel through the component interconnections, into those cells associated with inputs pins; and
2. To allow the components on the board to be tested, the boundary-scan register can be used as a means of isolating on-chip system logic from stimuli received from surrounding components, while an internal self-test is performed. Alternatively, when the boundary-scan register is suitably designed, it can permit a limited slow-speed static test of the on-chip system logic, since it allows delivery of test data to the component and examination of the test results. (IEEE std. 1149.1-1990, page 1-5)

The Intel Xscale® core does not support the second goal, because it does not support the optional INTEST or RUBIST instructions. The Intel Xscale® core is not required to provide these instructions, however, since it doesn't, this makes the following statement practically invalid.

The IEEE std. 1149.1 description of the SAMPLE/PRELOAD instruction states that, "When the SAMPLE/PRELOAD instruction is selected, the state of all signals flowing through system pins (input or output) shall be loaded into the boundary scan register on the rising edge of the TCK in the Capture-DR controller state." (Page 7-8).

The boundary scan cells of the Intel Xscale® core bi-directional pads, do not capture the data driven from the on-chip system logic to the pins, when these pads are acting as outputs. This would only be useful when trying to capture the data driven from the on-chip logic, during normal operation of the assembled board. However, the Intel Xscale® core does not allow single stepping of its clocks. Thus, even when the Intel Xscale® core did provide the compliant boundary scan cell, it would be extremely difficult (or impossible) to synch the boundary scan logic with the state of the on-chip logic. Therefore, this feature of the boundary scan cells is not useful. This has NO effect on the ability to determine the integrity of the interconnections on boards, which is what the Intel Xscale® core boundary scan logic was designed to support.

Workaround: No workaround.

Status: [NoFix](#).

2. Drain Is Not Flushed Correctly when Stalled in the Pipeline

Problem: In a load followed by a drain scenario, the load table walks and then gets a precise data abort. The core fetches the address for the abort handler, but in the same cycle does not flush the drain.

Implication: Not a functional problem, but may effect performance.

Workaround: No workaround.

Status: [NoFix](#).

3. Undefined Data Processing-‘like’ Instructions are Interpreted as an MSR Instruction

Problem: The instruction decode allows undefined opcodes, which look similar to the MSR (Move to Status register from an ARM register) instruction, to be interpreted as an MSR instruction. The mis-decoded MSR instruction also adds a SUBNV PC,0x4 to the instruction flow.

Workaround: Do not use undefined opcodes of this form:

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
-	-	-	-	0	0	0	1	0	-	1	0	-	-	-	-	-	-	-	-	-	-	-	-	0	0	1	0	-	-	-	-
-	-	-	-	0	0	0	1	0	-	1	0	-	-	-	-	-	-	-	-	-	-	-	-	0	1	0	0	-	-	-	-
-	-	-	-	0	0	0	1	0	-	1	0	-	-	-	-	-	-	-	-	-	-	-	-	0	1	1	0	-	-	-	-

Status: NoFix.

4. Debug Unit Synchronization with the TXRXCTRL Register

Problem: The RX bit in the TXRXCTRL (TX/RX Control) register comes from the JTAG clock domain to the core clock domain, and several cycles are needed for the register in the core clock domain to update. During this time, a debugger, which is running a fast JTAG clock relative to the core clock, may read the bit before it updates in the register, thus reading the old value.

Workaround: The JTAG clock should be slower than the core clock.

Status: NoFix.

5. Extra Circuitry Is Not JTAG Boundary Scan Compliant

Problem: The IEEE 1149.1 (JTAG) specification states that, “when the HIGHZ instruction is selected, all system logic outputs.... shall immediately be placed in an inactive drive state”. The JTAG unit on the core creates an internal ‘float’ signal, which is driven to the I/O pads. This signal is derived from the HIGHZ instruction; however, the HIGHZ instruction gets flopped by a rising edge of TCK first, before it is able to ‘float’ the pads. This is in violation of the JTAG specification, specifically the term “immediately”. It is possible for TCK to stop after the HIGHZ instruction is loaded and thus the pads may never ‘float’.

Workaround: Do not stop the JTAG clock (TCK).

Status: NoFix.

6. Incorrect Decode of Unindexed Mode, Using Addressing Mode 5, Can Corrupt Protected Registers

Problem: The instruction decoder incorrectly decodes the valid combination of P=0, U=1 and W=0, when using unindexed mode in addressing mode 5 (load and store coprocessor). In this case, the LDC or STC should produce consecutive address loads or stores, with no base update until the coprocessor signals that it has received enough data. Instead, the instruction gets separated into an LDR/STR and a CP access.

The LDR/STR gets decoded as a post-index address, updating the base register. Due to the decoding as post-index, the 'option' bits, normally reserved for the coprocessor in unindexed mode, become the 8-bit offset value used in the base register update calculation.

The implication is, that protected registers can be corrupted. This errata can cause the corruption of FIQ registers, R13-R14, in user and system modes when the LDC instruction is executed using unindexed addressing mode. It can also cause the corruption of FIQ registers, R8-R12, in any mode, when the LDC instruction is executed using unindexed addressing. The R13 register in debug mode may also be corrupted during an LDC in any mode. In the case of STC, only Rn is corrupted.

Unexpected memory accesses can also occur. In the case of an LDC, any memory location may be accessed, since the FIQ registers may be improperly used as the base register. In the case of an STC, the memory word located at Rn+4 is corrupted. This is the memory location immediately following the locations which should be modified by STC unindexed.

Workaround: Do not use unindexed addressing in addressing mode 5 – Load and Store Coprocessor.

Status: [NoFix](#).

7. Load Immediately Following a DMM Flush Entry is Also Flushed

Problem: A load that immediately follows a data memory management (DMM) flush entry command, that also hits the data TLB, is also flushed. Therefore, the instruction immediately following the flush, is also flushed from the data TLB.

Workaround: All flush entry commands to the data TLB must be followed by two NOPs. The first ensures the erratum is not encountered, and the second ensures the speed path is not hit.

Status: [NoFix](#).

8. Trace Buffer Does Not Operate Below 1.3 V

Problem: The trace buffer within the debug unit is not guaranteed to operate, due to voltage sensitivity, when the core voltage supply is below 1.3 V.

Workaround: Make sure the voltage is above 1.3 V during debug.

Status: [NoFix](#).

9. Data Cache Unit Can Stall for a Single Cycle

Problem: When the data cache unit retries an operation that is in the pending buffer, a single cycle stall occurs.

Workaround: No workaround. This is a performance issue only.

Status: [NoFix](#).

10. Aborted Store that Hits the Data Cache May Mark Writeback Data As Dirty

Problem: When there is an aborted store that hits clean data in the data cache (data in an aligned four word range, that has not been modified from the core, since it was last loaded in from memory or cleaned), the data in the array is not modified (the store is blocked), but the dirty bit is set.

When the line is then aged out of the data cache or explicitly cleaned, the data in that four word range is evicted to external memory, even though it has never been changed. In normal operation, this is nothing more than an extra store on the bus, that writes the same data to memory as is already there.

Here is the boundary condition where this might be visible:

1. a cache line is loaded into the cache at address A
2. another master externally modifies address A
3. a core store instruction attempts to modify A, hits the cache, aborts because of MMU permissions, and is backed out of the cache. That line should not be marked dirty, but because of this errata is marked as dirty.
4. the cache line at A then ages out or is explicitly cleaned. The original data from location A is evicted to external memory, overwriting the data written by the external master.

This only happens when software is allowing an external master to modify memory, that is, writeback or write-allocate in the page tables, and depending on the fact that the data is not 'dirty' in the cache, to preclude the cached version from overwriting the external memory version. When there are any semaphores or any other handshaking to prevent collisions on shared memory, this should not be a problem.

Workaround: For this shared memory region, mark it as write-through memory in the page table. This prevents the data from ever being written out as dirty.

Status: [NoFix](#).

11. Performance Monitor Unit Event 0x1 Can Be Incremented Erroneously by Unrelated Events

Problem: Event 0x1 in the performance monitor unit (PMU) can be used to count cycles in which the instruction cache cannot deliver an instruction. The only cycles counted should be those due to an instruction cache miss or an instruction TLB miss. The following unrelated events in the core, also causes the corresponding count to increment when event number 0x1 is being monitored:

1. Any architectural event (e.g. IRQ, data abort)
2. MSR instructions which alter the CPSR control bits
3. Some branch instructions, including indirect branches and those mispredicted by the BTB
4. CP15 mcr instructions to registers 7, 8, 9, or 10 which involve the instruction cache or the instruction TLB.

Each of the items above may cause the performance monitoring count to increment several times. The resulting performance monitoring count may be higher than expected when the above items occur, but never lower.

Workaround: There is no way to obtain the correct number of cycles stalled due to instruction cache misses and instruction TLB misses. Extra counts due to branch instructions mispredicted by the BTB, may be one component of the unwanted count that can be filtered out. The number of mispredicted branches can also be monitored using performance monitoring event 0x6 during the same time period as event 0x1. The mispredicted branch number can then be subtracted from the instruction cache stall number generated by the performance monitor to get a value closer to the correct one. Note that this only addresses counts contributed by branches that the BTB is able to predict. All the items listed above still affect the count. Depending on the nature of the code being monitored, this workaround may have limited value.

Status: [NoFix](#).

12. In Special Debug State, Back-to-Back Memory Operations Where the First Instruction Aborts May Cause a Hang

Problem: When back-to-back memory operations occur in the Special Debug State (SDS, used by ICE and Debug vendors) and the first memory operation gets a precise data abort, the first memory operation is correctly cancelled and no abort occurs. However, depending on the timing, the second memory operation may not work correctly. The data cache may internally cancel the second operation, but the register file may have score-boarded registers for that second memory operation.

The effect is that the core may hang (due to a permanently score-boarded register) or that a store operation may be incorrectly cancelled.

Workaround: In Special Debug State, any memory operation that may cause a precise data abort should be followed by a write-buffer drain operation. This precludes further memory operations from being in the pipe when the abort occurs. Load Multiple/Store Multiple that may cause precise data aborts should not be used.

Status: [NoFix](#).

13. Accesses to the CP15 ID register with opcode2 > 0b001 returns unpredictable values

Problem: The *ARM Architecture Reference Manual* (ARM DDI 0100E) states the following in chapter B-2, section 2.3:

“If an <opcode2> value corresponding to an unimplemented or reserved ID register is encountered, the System Control processor returns the value of the main ID register.

ID registers other than the main ID register are defined so that when implemented, their value cannot be equal to that of the main ID register. Software can therefore determine whether they exist by reading both the main ID register and the desired register and comparing their values. If the two values are not equal, the desired register exists.”

The Intel Xscale® core does not implement any CP15 ID code registers other than the Main ID register (opcode2 = 0b000) and the Cache Type register (opcode2 = 0b001). When any of the unimplemented registers are accessed by software (e.g., mrc p15, 0, r3, c15, c15, 2), the value of the Main ID register should be returned. Instead, an unpredictable value is returned.

Workaround: No workaround.

Status: NoFix.

14. Disabling and re-enabling the MMU can hang the core or cause it to execute the wrong code

Problem: When the MMU is disabled, via the CP15 control register (CP15, CR1, opcode_2 = 0, bit 0), after being enabled, certain timing cases can cause the processor to hang. In addition to this, re-enabling the MMU after disabling it can cause the processor to fetch and execute code from the wrong physical address. To avoid these issues, the code sequence below needs to be used whenever disabling the MMU or re-enabling it afterwards.

Workaround: The following code sequence can be used to disable and/or re-enable the MMU safely. The alignment of the mcr instruction that disables or re-enables the MMU needs to be controlled carefully, so that it resides in the first word of an instruction cache line.

@ The following code sequence takes r0 as a parameter. The value of r0 is written
@ to the CP15 control register to either enable or disable the MMU.

```
mcr    p15, 0, r0, c10, c4, 1@ unlock I-TLB
mcr    p15, 0, r0, c8, c5, 0@ invalidate I-TLB

      mrc p15, 0, r0, c2, c0, 0@ CPWAIT
      mov r0, r0
      sub pc, pc, #4

b      1f                @ branch to aligned code

.align 5
1:
mcr    p15, 0, r0, c1, c0, 0@ enable/disable MMU, caches

      mrc p15, 0, r0, c2, c0, 0@ CPWAIT
      mov r0, r0
      sub pc, pc, #4
```

Status: NoFix.

15. Updating the JTAG parallel register requires an extra TCK rising edge

Problem: IEEE 1149.1 states that the effects of updating all parallel JTAG registers should be seen on the falling edge of TCK in the Update-DR state. The Intel Xscale® core parallel JTAG registers incorrectly require an extra TCK rising edge to make the update visible. Therefore, operations like hold-reset, JTAG break, and vector traps require either an extra TCK cycle by going to Run-Test-Idle or by cycling through the state machine again in order to trigger the expected hardware behavior.

Workaround: When the JTAG interface is polled continuously, this erratum has no effect. When not, an extra TCK cycle can be caused by going to Run-Test-Idle after writing a parallel JTAG register.

Status: [NoFix](#).

Non-Core Errata

1. The ATU Returns Invalid Data for the DWORD that Target Aborted from the MCU when Using 32-Bit Memory, ECC Enabled and in PCI Mode

The external PCI bus requests a read through the ATU to the MCU, starting at the high DWORD. Remember the MCU is in 32-bit mode. The ATU requests multiple DWORDs since it pre-fetches, but starts at the high DWORD address. The MCU issues two DWORDs. First the high, followed by the low and then a Target Abort, so the DWORD count is two. When the ATU returns the data to the external PCI agent (in PCI Mode ONLY), the logic ONLY disconnects on 64-byte QWORD boundaries. Recall the ATU DWORD count is at two. When the external PCI device returns to get data, the ATU returns the first DWORD and SHOULD disconnect, because it does not have enough data to get to the next QWORD boundary. It does not do this. Instead, it returns invalid data in the high DWORD of the second QWORD (data from a previous fetch) and the transaction is corrupted.

This issue occurs when all of the following conditions exist in the MCU:

1. 32-bit memory
2. ECC is enabled
3. The PCI bus is in PCI mode

Workaround: Use 64-bit Memory, PCI-X Mode or ECC disabled.

Status: [NoFix](#).

2. PBI Issue When Using 16-bit PBI Transactions in PCI Mode

Problem: Under certain conditions, in bound burst and non-burst reads and writes from the PCI bus to the PBI would appear as two writes on the PBI. However, the byte enables are not asserted for the second write.

This happens when:

1. 80219 is in PCI mode.
2. Another PCI master is attempting to access the PBI behind the 80219.
3. 16-bit mode on PBI.

Workaround: The BE# signals can be used in combination with the PCE#. The BE# prevents the second CE# from being recognized by the Flash. See the Intel® IQ80219 evaluation platform board (IQ80219) schematic for a circuit design to correct this issue.

Status: [NoFix](#).

3. MCU Pointers are Incorrect following a Restoration from a Power Fail

Problem: This issue occurs when:

1. There is a power failure (not during power management or normal shutdown).
2. When power is restored, the internal MCU pointers to the SDRAM may not be correct.
3. When a read from SDRAM (prior to doing a write to SDRAM) is the first MCU operation done after the power is restored, the MCU pointers may be incorrect and can be reading the wrong data.
4. However, when a write to SDRAM is the first MCU operation done after the power is restored, then the pointers are correct and everything works properly.

Workaround: Following restoration of power after a power failure, ensure that the first MCU operation done is a write to SDRAM.

Status: [NoFix](#).

4. PMU Does Not Account for when the Arbiter Deasserts GNT# One Cycle before FRAME#

Problem: One of the countable PMU events is bus acquisition latency for the ATU. There is a condition where the acquire counter is not stopped even though the ATU starts a transaction. When the arbiter deasserts GNT# in PCI-X mode, the requestor can still start a transaction for one cycle (due to allowed pipelining). In this situation, the PMU does not properly detect the FRAME# as the ATU and continues running the counter.

Workaround: No workaround.

Status: [NoFix](#).

5. Lost Data During Bursts of Large Number of Partial with 32-bit ECC Memory

Problem: When the MCU operates in 32-bit mode only and it is hit by enough partials to cause the input posted write buffer to fill (in 32-bit mode it holds 512 bytes), the MCU has conditions where it does NOT disconnect on the IB (internal bus) before overrunning.

When the buffer overruns, the MCU momentarily thinks it is empty, allowing the refresh to occur, but also causing all data to be lost for the rest of the burst. The ATU continues to throw data at the MCU, but this data is lost.

This is strictly a 32-bit memory ECC on mode issue, as this is the only way to fill the entire buffer since all buffers on the IB are 1 K in size (except the MCU when operating in 32-bit DDR mode). The DMA, AAU, and core cannot cause the situation in 32-bit mode because they only issue up to two partials in their burst before disconnecting. In these situations, the MCU will drain enough data to prevent buffer overrun.

Workaround: Use 64-bit memory or ECC disabled.

Status: [NoFix](#).

6. The MTTR1 (Core Multi-Transaction Timer) is not operating due to improper behavior of the core internal bus request signal (REQ#)

Problem: The MTTR1 (Core Multi-Transaction Timer) is not operating due to improper behavior of the core internal bus request signal (REQ#). All agents on the bus, except the core, maintain their assertion on REQ# signals upon receiving a retry. When the MCU is busy this means that the core must wait for other agents to complete their transactions before the core gains access to memory. Due to the fact that internal bus agents initiate larger transactions than the core, this issue results in an unbalanced access to the internal bus biased to these other agents (DMA, ATU, etc.). When operational, the MTTR1 is intended to correct this balance. See Section 11.2.2 of the *Intel® 80219 General Purpose PCI Processor Developer's Manual* for more information on the MTTR1 function.

Implication: In the case of the MCU internal bus target, this problem is compounded by the many internal bus retries that are issued by the MCU when under heavily loaded conditions. The result is that the internal bus arbiter removes the core access to the bus when the core deasserts REQ#. This condition may result in the core being locked out of accessing the MCU until other internal bus agents have completed their transaction(s) (i.e., when the DMA is in the process of a large block transfer of data, the core may have to wait until the DMA transaction is completed before it would have access to the internal bus to initiate its transaction).

Workaround: No workaround.

Status: [NoFix](#).

7. The MCU supports a page size of 2 Kbytes for 64-bit mode

Problem: The *Intel® 80219 General Purpose PCI Processor Developer's Manual* (Section 6.1.1 and Section 6.2.2.3) states that the MCU supports a page size of 4 Kbytes for 64-bit mode and 2 Kbytes for 32-bit mode. This is in error.

Implication: The MCU supports a page size of 2 Kbytes for 64-bit mode and for 32-bit mode.

Workaround: No workaround.

Status: [NoFix](#).

8. Vih Minimum Input High Voltage (Vih) level for the PCI pins

Problem: The Vih Minimum Input High Voltage (Vih) level for the PCI pins is being tested at 100 mV higher than the minimum Vih level specified in Table 4-3 (DC Specifications for 3.3 V Signaling) of the *PCI Local Bus Specification*, Revision 2.2. This Vih test limit only applies to cold temperature testing specified to be 0°C.

The *PCI Local Bus Specification*, Revision 2.2 specifies the minimum Vih level to be 0.5 Vcc. The Vcc specification is 3.3 V +/- 10% with the minimum Vcc specification (or minimum power level) being tested at 3.0 V. The minimum Vih level per the PCI Specification should therefore be 0.5(3.0 V) or 1.5 V. The 80219 is unable to meet this minimum Vih level at cold temperature testing specified to be 0°C.

Implication: During cold temperature manufacturing testing, 80219 silicon is subjected to a 0°C environment for an extended period of time. During this time the Vih test is implemented and the junction temperature is at or near the test temperature of 0°C. This junction temperature is considered to be far less than the temperature the 80219 silicon would be subjected to in a customer application under operating conditions.

Below is an example calculation showing the expected junction temperature for a customer application operating in an ambient temperature of 0°C:

Tj = junctions temperature, Ta = ambient temperature, qja = junction to ambient thermal resistance of the package, P = power at minimum Vcc

$T_j = T_a + (q_{ja} * P)$ where Ta = 0C, qja = 13.94 C/W assuming 200lfm airflow (see Table 11 of the *Intel® 80219 General Purpose PCI Processor Datasheet*), P = 3.0 W

$T_j = 0 + (13.94 \text{ C/W} * 3.0 \text{ C})$

Tj = 41.82 C

Workaround: The minimum Vih level for the PCI pins will be tested at the *PCI Local Bus Specification*, Revision 2.2 specification (0.5 Vcc) plus an additional 100 mV that equates to 1.6 V during cold temperature manufacturing testing.

Status: NoFix.



Specification Changes

1. **Signal NC2 was renamed to P_BMI (AE23). New function added to signal P_BMI.**

The P_BMI (AE23) signal has been added to the Intel® 80219 general purpose PCI processor. This signal replaces, using an external GPIO pin for Initialization Device Select (IDSEL) control of an I/O device during host configuration cycles.

Issue: I/O Device IDSEL control using the new P_BMI signal:

When the system boots after reset, the host BIOS initiates a PCI bus scan to find all the PCI components installed in the system. The system uses the IDSEL signal to address the I/O device when assigning the necessary resources. Without special control over the IDSEL signal during configuration cycles, the host and the 80219 may both attempt to configure the same I/O device. By taking control of IDSEL, the 80219 can execute configuration cycles to the slave I/O device (SCSI) and properly hide the slave I/O device from the host and operating system initiated configuration cycles.

The 80219 has eight integrated General Purpose Input Output (GPIO) pins, referred to as GPIO[7:0]. These pins, along with the new PCI-X Bus Master Indicator (P_BMI) signal, can be used to control the IDSEL to the I/O device. External circuitry is no longer required other than a simple switch. The output function of the P_BMI signal is controlled by the GPIO Output Data Register (GPOD), Bit 0 as shown in Table 1. The P_BMI signal is always driven and defaults to driving low at power up.

Table 1. **GPIO Output Data Register (address = FFFF E7CCh)**

Bit	Default	Description
0	0	This bit value is driven on the P_BMI signal when the 80219 has been given control of the bus (granted GNT#) by the bus arbiter.

The IDSEL signal is used as a chip select during configuration cycles initiated by the BIOS, operating system or 80219. The GPOD[0] can be driven low in firmware, thereby disabling the P_BMI signal and hiding the host I/O device from the system, by turning off its IDSEL. When the 80219 intends to perform configuration cycles in the PCI bus segment of the I/O device, the P_BMI signal should be asserted high by driving the GPOD[0] high. The affect of these two operations is, that the I/O device is initialized and controlled by the 80219. More care must be taken with the gate chosen to control IDSEL, since most host bridge controllers do not use PCI address stepping. With IDSEL being a synchronous signal, with respect to CLK, the switch used must be a sub nanosecond propagation delay device (e.g., Pericom PI5C3303). In Figure 2, the P_BMI signal is used to control a MUX/DeMUX switch that is used to enable/disable IDSEL to the I/O device.

Figure 2. Intel® 80219 General Purpose PCI Processor P_BMI Signal Implementation for Intel® 80219 General Purpose PCI Processor B-0/B-1 Stepping



Specification Clarifications

1. The Intel® 80219 general purpose PCI processor is compliant with the PCI Local Bus Specification, Revision 2.2 but it is not compliant with PCI Local Bus Specification, Revision 2.3

Issue: The Intel® 80219 general purpose PCI processor was designed to be compliant with the *PCI-X Addendum to the PCI Local Bus Specification*, Revision 1.0a, that calls out compliance with the *PCI Local Bus Specification*, Revision 2.2. Since the release of the 80219, the PCI Special Interest Group has released a new specification revision, *PCI Local Bus Specification*, Revision 2.3.

Status: **NoFix.** The current stepping of the 80219 is not compliant with *PCI Local Bus Specification*, Revision 2.3 and there are no plans to make it compliant with the *PCI Local Bus Specification*, Revision 2.3 in future steppings.

2. Modifications to the Hot-Debug procedure are necessary for the Intel® 80219 general purpose PCI processor when flat memory mapping is not used (Virtual Address = Physical Address)

Issue: The Intel® 80219 general purpose PCI processor can implement Hot Debug as stated in the application note “*Hot-Debug for Intel® Xscale™ Core Debug*”: [“http://developer.intel.com/design/iio/applnots/273539.htm”](http://developer.intel.com/design/iio/applnots/273539.htm).

However, there can be a conflict for resources when flat memory mapping is not used (Virtual Address = Physical Address).

This is primarily due to the debug implementation within the core that causes the Instruction Memory Management Unit to be disabled when in this Special Debug State.

Status: **NoFix.** The following are suggested steps to overcome this conflict within a debug environment.

1. Instrument the application code to add an infinite loop before any memory is remapped (physically or virtually).
2. Hook up the JTAG Debugger that supports Hot Debug.
3. Set PC to address passed the loop.
4. The code can now run without the need to reset the application environment.

Note: Once a debug session has ended, you must follow the above steps over again in order to regain debug control.

3. BAR0 Configuration When Using the Messaging Unit (MU)

Issue: When the BAR0 is configured as a prefetchable register by default and a burst request crosses into or through the range of offsets 40h to 4Ch (i.e., this includes the Circular Queues), the transaction is signaled a Target Abort immediately on the PCI/PCI-X bus, which may be read as an NMI by the host BIOS.

Status: **Doc.** Do not configure the BAR0 as prefetchable when using BAR0 and the non-prefetchable MU registers (i.e., range of offsets 40h to 4Ch). Configure the BAR0 as non-prefetchable, IABAR0[3], when accessing these non-prefetchable MU registers. Since non-prefetchable memory windows cannot be placed above the 4 Gbyte address boundary, when the Prefetchable Indicator bit, IABAR0[3], is cleared prior to host configuration, also clear the Type Indicator bits, IABAR0[2:1] for 32-bit addressability. When the non-prefetchable MU registers are in use, those memory accesses that require prefetchable operations, use the BAR2 configured as prefetchable.

4. Reading Unpopulated SDRAM Memory Banks

Issue: A hang condition can occur with the 80219 when firmware does a read to unpopulated SDRAM memory and DQS0 is sampled low. In this scenario, putting a load (i.e., scope probe), on the DQS0 signal could trigger DQS0 to be sampled low, which the MCU interprets as the pre-amble and waits for DQS0 to go high. Since the read is to unpopulated memory, nothing drives the DQS0 signal high, therefore the 80219 appears to hang.

Status: **Doc.** Do not attempt to read from non-existent memory. In some applications, firmware performs a memory scan, typically during boot-up, to determine the total amount of SDRAM installed. Instead, either use the Serial Presence Detect (SPD) mechanism or have it hard coded in firmware. SPD is used to read, via I²C, from a non-volatile storage device. This device contains data programmed by the DIMM manufacturer, that identifies the module type, various SDRAM organizations and timing parameters. Using SPD or hard coded firmware eliminates the need to do SDRAM sizing in the firmware.

5. 32-bit Writes-to-Unaligned 64-bit Addresses, are Promoted to 64-bit Aligned Writes

Issue: In 80219-based applications that run the PCI bus segment in 32-bit PCI Mode or 64-bit PCI Mode with 32-bit targets, write transactions that are on unaligned 64-bit addresses are promoted to 64-bit aligned writes. The first half of the 64-bit write is on a 64-bit aligned address and has the BE# signals disabled. Therefore, the write is invalid. The second half on the 64-bit write is a valid write with the BE# enabled and the write is to the intended 32-bit address.

Per the *PCI Local Bus Specification*, Revision 2.2, the PCI compliant devices should ignore the first half of the 64-bit write due to the BE# signals being disabled.

Status: For devices that support using the I/O memory window, the 64-bit write does not occur when using the 80219 ATU I/O Window and the only expected 32-bit write occurs. See section 3.2.2.2 of the *Intel® 80219 General Purpose PCI Processor Developer's Manual* for details.

For memory mapped devices, the only option is to run in PCI-X mode, where the byte count and starting address are consistent with the actual number of bytes to be written (i.e., 4). This is so because, when a 64-bit PCI-X request gets downshifted, the requester can use the starting address/byte count to recognize that the write request does not cross a DWORD address boundary and only perform a single 32-bit wide data cycle.

6. In-order Delivery not guaranteed for data blocks described by a single DMA descriptor

Issue: In-order delivery is not guaranteed for data blocks described by a single DMA descriptor that crosses a 1 KB boundary. This may result in out of order execution of the DMA transfer. When multiple DMA descriptors are used the ordering is maintained with respect to the blocks described by each descriptor. When ordering is important, the ordering needs to be maintained by splitting the relevant pieces of data into multiple DMA descriptors.

Example A 100 byte DMA transfer described by a single descriptor with a source address of 0x3ff8. Since each DMA channel has two 1 KB buffers, the DMA unit breaks this transaction at the 1 KB boundary. Therefore, the first buffer might fetch the 8 bytes from 0x3ff8-0x3fff and the second buffer might fetch the remaining 92 bytes from 0x4000-0x405C. Both buffers have the ability to access the internal bus, without preference (i.e., either buffer may gain access first). Therefore, it is possible the 92 bytes of data after the 1 KB boundary could be transferred to the destination before the first 8 bytes. However, the transaction is completed and all data has been copied to the correct address when the descriptor completes (i.e., descriptors are not completed out of order).

Status: When a data delivery sequence is required, descriptors should be used to ensure sequenced arrival (e.g., in the example above), break the data into blocks then use multiple descriptors linked in the correct order to ensure sequential data delivery.

7. Writing to reserved registers can cause unexpected behavior

Issue: The Intel® 80219 General Purpose PCI Processor contains several reserved registers. The *Intel® 80219 General Purpose PCI Processor Developer's Manual* (Section 15.5 Table 273) states that memory map register locations FFFFE800H - FFFFE8FFH are reserved. Writing to these can cause the processor to enter an undesired state.

Status: NoFix.

Documentation Changes

None for this revision of this specification update.



This Page Left Intentionally Blank