



## SMA Straight Cable Plug Solder Clamp Attachments 1050777–1, 1050787–1, 1050781–1, 1050789–1, and 1329374–1

Instruction Sheet 408–4918 (was A.P. 20–545) 04 APR 03 Rev A




Figure 1

#### 1. INTRODUCTION

This instruction sheet contains the assembly procedures for the SMA Straight Cable Plug Solder Clamp Attachments 1050777–1, 1050787–1, 1050781–1, 1050789–1, and 1329374–1 which are applied onto RG 405/U (.085) semi–rigid coaxial cable.

The table in Figure 2 represents tool numbers applicable to this instruction sheet. The table references the previous part number to the Tyco Electronics part number.

TOOL DESCRIPTION	TYCO ELECTRONICS PART NUMBER	PREVIOUS PART NUMBER	
Fixture Base	1055439–1	2098–5206–54	
Clamp Inserts	1055441–1	2098–5208–54	
Center Contact Holder	1055454–1	2098–5221–10	
Locator Tool (Optional)	1055507–1	2098–5605–02	

Figure 2

NOTE

Dimensions on this instruction sheet are in millimeters [with inches in brackets]. Figures are not drawn to scale.

Reasons for reissue of this document are provided in Section 5, REVISION SUMMARY.

## 2. **DESCRIPTION** (Figure 1)

The SMA straight cable plug solder clamp attachments consist of a housing sub-assembly, dielectric, center contact, rear dielectric, inner sleeve, and clamp nut.

### 3. ASSEMBLY PROCEDURES

## 3.1. Preparing the Cable (Figure 3)

- 1. Insert squared cable end into fixture base hole pattern No. 2.
- 2. Place saw in saw slot and cut through outer conductor and into dielectric while rotating cable.
- 3. Remove cable from fixture and finish cutting dielectric with cutting blade.
- 4. Bare inner conductor by prying cut outer conductor and dielectric from cable.
- 5. Complete trimming of cable inner conductor to dimension shown in Figure 3.




Figure 3

## 3.2. Soldering of Inner Sleeve to Cable (Figure 4)

- 1. Place clamp nut and inner sleeve on end of cable.
- 2. Place loose assembly in fixture base as shown in Figure 4. (Slide clamp nut back out of way.)
  - a. Nest cable in locator tool.

www.tycoelectronics.com



- b. Tighten clamp screw to secure cable.
- c. Tighten locator tool to seat cable firmly.
- 3. Slide inner sleeve against locator tool.
- 4. Maintain position of inner sleeve firmly against locator tool and solder.

NOTE

Fixture base should be clamped vertically in vise to keep inner sleeve seated against locator tool.

CAUTION

Damaged components must not be used. They must be replaced with new components.




Figure 4

# 3.3. Soldering of Center Contact to Cable Inner Conductor (Figure 5)

- 1. Tin inner conductor of cable.
- 2. Place rear dielectric onto cable inner conductor.
- 3. Place center contact in holder. Heat center contact and push it over inner conductor of cable with the large diameter of contact resting firmly against rear dielectric.
- 4. Remove excess solder.

## 3.4. Secure Inner Sleeve Sub-Assembly to Housing (Figure 6)

- 1. Assemble front dielectric onto center contact.
- 2. Slide clamp nut over inner sleeve and engage threads of clamp to housing. Torque to 2.83 − 3.39 N•m [25 − 30 in−lb].
- 3. Assembly is now complete.




Figure 5




Figure 6

#### 4. MILITARY INFORMATION

TYCO ELECTRONICS PART NUMBER	MILITARY P/N M39012/79	PREVIOUS PART NUMBER
1050777–1	B3003	2001–8003–92
1050787–1	B3103●	2001–8103–92
1050781–1 1329374–1	-3007	2001–8007–92
1050789–1	-3107◆	2001–8107–92

No safety wire holes.

#### 5. REVISION SUMMARY

Revisions to this instruction sheet per EC 0990–0259–03 include:

- Updated document to corporate requirements
- Updated artwork to make document easier to read

**2** of 2 Rev **A**