

## PV36 Series

### ■ Features



1. High resolution 25-turns enables precision adjustment easily.
2. Sealed construction protects the interior from dust and liquid, which achieves stable performance.
3. Available for ultrasonic cleaning after soldering
4. Clutch mechanism prevents excessive wiper rotation.
5. 5 standard terminal styles
6. Both Top and side adjustment directions.
7. To be complied with RoHS directive by new Cd free cermet resistive material. Pb free terminals with Sn plating.

### ■ Applications



1. Measuring instruments
2. OA equipment
3. Medical equipment
4. Power supply
5. Base station for cellular phone





PV36P




PV36W





PV36X



PV36Y



PV36Z



| Part Number | Power Rating | Soldering Method    | Number of Turns<br>(Effective Rotation Angle) | Total Resistance Value | TCR        |
|-------------|--------------|---------------------|-----------------------------------------------|------------------------|------------|
| PV36□100C01 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 10ohm ±10%             | ±150ppm/°C |
| PV36□200C01 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 20ohm ±10%             | ±150ppm/°C |
| PV36□500C01 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 50ohm ±10%             | ±150ppm/°C |

Continued on the following page.

Continued from the preceding page.

| Part Number | Power Rating | Soldering Method    | Number of Turns<br>(Effective Rotation Angle) | Total Resistance Value | TCR        |
|-------------|--------------|---------------------|-----------------------------------------------|------------------------|------------|
| PV36□101C01 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 100ohm ±10%            | ±150ppm/°C |
| PV36□201C01 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 200ohm ±10%            | ±100ppm/°C |
| PV36□501C01 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 500ohm ±10%            | ±100ppm/°C |
| PV36□102C01 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 1k ohm ±10%            | ±100ppm/°C |
| PV36□202C01 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 2k ohm ±10%            | ±100ppm/°C |
| PV36□502C01 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 5k ohm ±10%            | ±100ppm/°C |
| PV36□103C01 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 10k ohm ±10%           | ±100ppm/°C |
| PV36□203C01 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 20k ohm ±10%           | ±100ppm/°C |
| PV36□253C01 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 25k ohm ±10%           | ±100ppm/°C |
| PV36□503C01 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 50k ohm ±10%           | ±100ppm/°C |
| PV36□104C01 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 100k ohm ±10%          | ±100ppm/°C |
| PV36□204C01 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 200k ohm ±10%          | ±100ppm/°C |
| PV36□254C01 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 250k ohm ±10%          | ±100ppm/°C |
| PV36□504C01 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 500k ohm ±10%          | ±100ppm/°C |
| PV36□105C01 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 1M ohm ±10%            | ±100ppm/°C |
| PV36□205C01 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 2M ohm ±10%            | ±100ppm/°C |
| PV36□100C31 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 10ohm ±10%             | ±150ppm/°C |
| PV36□200C31 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 20ohm ±10%             | ±150ppm/°C |
| PV36□500C31 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 50ohm ±10%             | ±150ppm/°C |
| PV36□101C31 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 100ohm ±10%            | ±150ppm/°C |
| PV36□201C31 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 200ohm ±10%            | ±100ppm/°C |
| PV36□501C31 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 500ohm ±10%            | ±100ppm/°C |
| PV36□102C31 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 1k ohm ±10%            | ±100ppm/°C |
| PV36□202C31 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 2k ohm ±10%            | ±100ppm/°C |
| PV36□502C31 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 5k ohm ±10%            | ±100ppm/°C |
| PV36□103C31 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 10k ohm ±10%           | ±100ppm/°C |
| PV36□203C31 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 20k ohm ±10%           | ±100ppm/°C |
| PV36□253C31 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 25k ohm ±10%           | ±100ppm/°C |
| PV36□503C31 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 50k ohm ±10%           | ±100ppm/°C |
| PV36□104C31 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 100k ohm ±10%          | ±100ppm/°C |
| PV36□204C31 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 200k ohm ±10%          | ±100ppm/°C |
| PV36□254C31 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 250k ohm ±10%          | ±100ppm/°C |
| PV36□504C31 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 500k ohm ±10%          | ±100ppm/°C |
| PV36□105C31 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 1M ohm ±10%            | ±100ppm/°C |
| PV36□205C31 | 0.5W(70°C)   | Flow/Soldering Iron | 25                                            | 2M ohm ±10%            | ±100ppm/°C |

Operating Temperature Range: -55 to 125 °C


The blank column is filled with the code of adjustment direction and lead type (P, X, Y, W and Z).

The order quantity should be an integral multiple of the "Minimum Quantity".

The last three digits express the individual specification codes. C01 for standard type and C31 for radial taping type (PV36W/PV36X series only).


| Part Number | Power Rating (W) | Soldering Method    | Number of Turns (Effective Rotation Angle) | Total Resistance Value | TCR (ppm/°C) | Remarks                            |
|-------------|------------------|---------------------|--------------------------------------------|------------------------|--------------|------------------------------------|
| PV36□100A01 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 10 ohm±10%             | ±100         | Non Standard Product (Cd included) |
| PV36□200A01 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 20 ohm±10%             | ±100         |                                    |
| PV36□500A01 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 50 ohm±10%             | ±100         |                                    |
| PV36□101A01 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 100 ohm±10%            | ±100         |                                    |
| PV36□201A01 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 200 ohm±10%            | ±100         |                                    |
| PV36□501A01 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 500 ohm±10%            | ±100         |                                    |
| PV36□102A01 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 1k ohm±10%             | ±100         |                                    |
| PV36□202A01 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 2k ohm±10%             | ±100         |                                    |
| PV36□502A01 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 5k ohm±10%             | ±100         |                                    |
| PV36□103A01 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 10k ohm±10%            | ±100         |                                    |
| PV36□203A01 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 20k ohm±10%            | ±100         |                                    |
| PV36□253A01 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 25k ohm±10%            | ±100         |                                    |
| PV36□503A01 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 50k ohm±10%            | ±100         |                                    |
| PV36□104A01 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 100k ohm±10%           | ±100         |                                    |
| PV36□204A01 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 200k ohm±10%           | ±100         |                                    |
| PV36□254A01 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 250k ohm±10%           | ±100         |                                    |
| PV36□504A01 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 500k ohm±10%           | ±100         |                                    |
| PV36□105A01 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 1M ohm±10%             | ±100         |                                    |
| PV36□205A01 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 2M ohm±10%             | ±100         |                                    |
| PV36□100A31 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 10 ohm±10%             | ±100         |                                    |
| PV36□200A31 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 20 ohm±10%             | ±100         |                                    |
| PV36□500A31 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 50 ohm±10%             | ±100         |                                    |
| PV36□101A31 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 100 ohm±10%            | ±100         |                                    |
| PV36□201A31 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 200 ohm±10%            | ±100         |                                    |
| PV36□501A31 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 500 ohm±10%            | ±100         |                                    |
| PV36□102A31 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 1k ohm±10%             | ±100         |                                    |
| PV36□202A31 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 2k ohm±10%             | ±100         |                                    |
| PV36□502A31 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 5k ohm±10%             | ±100         |                                    |
| PV36□103A31 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 10k ohm±10%            | ±100         |                                    |
| PV36□203A31 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 20k ohm±10%            | ±100         |                                    |
| PV36□253A31 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 25k ohm±10%            | ±100         |                                    |
| PV36□503A31 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 50k ohm±10%            | ±100         |                                    |
| PV36□104A31 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 100k ohm±10%           | ±100         |                                    |
| PV36□204A31 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 200k ohm±10%           | ±100         |                                    |
| PV36□254A31 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 250k ohm±10%           | ±100         |                                    |
| PV36□504A31 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 500k ohm±10%           | ±100         |                                    |
| PV36□105A31 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 1M ohm±10%             | ±100         |                                    |
| PV36□205A31 | 0.5(70°C)        | Flow/Soldering Iron | 25                                         | 2M ohm±10%             | ±100         |                                    |

## ■ Construction




## ■ Mounting Holes

PV36P




(Tolerance: ±0.1  
in mm)

PV36W/X



(Tolerance: ±0.1  
in mm)

PV36Y/Z



(Tolerance: ±0.1  
in mm)

## ■ Characteristics

|                              |                 |                                                            |
|------------------------------|-----------------|------------------------------------------------------------|
| Temperature Cycle            | $\Delta TR$     | ±2%                                                        |
|                              | $\Delta V.S.S.$ | ±1%                                                        |
| Humidity                     | $\Delta TR$     | ±2%                                                        |
|                              | IR              | 100Mohm min.                                               |
| Vibration (20G)              | $\Delta TR$     | ±1%                                                        |
|                              | $\Delta V.S.S.$ | ±1%                                                        |
| Shock (100G)                 | $\Delta TR$     | ±1%                                                        |
|                              | $\Delta V.S.S.$ | ±1%                                                        |
| Temperature Load Life        | $\Delta TR$     | ±3%                                                        |
|                              | $\Delta V.S.S.$ | ±1%                                                        |
| Low Temperature Exposure     | $\Delta TR$     | ±2%                                                        |
|                              | $\Delta V.S.S.$ | ±1%                                                        |
| High Temperature Exposure    | $\Delta TR$     | ±3%                                                        |
|                              | $\Delta V.S.S.$ | ±1%                                                        |
| Rotational Life (200 cycles) | $\Delta TR$     | $R \leq 1\text{kohm}, R \geq 500\text{kohm} \dots \pm 5\%$ |
|                              |                 | $1\text{kohm} < R < 500\text{kohm} \dots \pm 3\%$          |

$\Delta TR$  : Total Resistance Change  
 $\Delta V.S.S.$  : Voltage Setting Stability  
 IR : Insulation Resistance  
 R : Standard Total Resistance

## PV12/PV37/PV23/PV22/PV36 Series Notice

### ■ Notice (Operating and Storage Conditions)

1. Store in temperatures of -10 to +40 deg. C and relative humidity of 30-85%RH.
2. Do not store in or near corrosive gases.
3. Use within six months after delivery.
4. Open the package just before using.
5. Do not store under direct sunlight.
6. If you use the trimmer potentiometer in an environment other than listed below, please consult with a Murata factory representative prior to using.  
The trimmer potentiometer should not be used under

the following environmental conditions:

- (1) Corrosive gaseous atmosphere  
(Ex. Chlorine gas, Hydrogen sulfide gas, Ammonia gas, Sulfuric acid gas, Nitric oxide gas, etc.)
- (2) In liquid  
(Ex. Oil, Medical liquid, Organic solvent, etc.)
- (3) Dusty / dirty atmosphere
- (4) Direct sunlight
- (5) Static voltage nor electric/magnetic fields
- (6) Direct sea breeze
- (7) Other variations of the above

### ■ Notice (Rating)

1. When using with partial load (rheostat), minimize the power depending on the resistance value.
2. The maximum input voltage to a trimmer potentiometer should not exceed  $(P/R)^{1/2}$  or the maximum operating voltage, whichever is smaller.
3. The maximum input current to a trimmer potentiometer should not exceed  $(P/R)^{1/2}$  or the allowable wiper current, whichever is smaller.

### ■ Notice (Soldering and Mounting)

#### 1. Soldering

##### (1) Standard soldering condition

##### (a) Flow soldering :

- >Pre-heating temp. 80-100 deg. C
- >Soldering temp. 260 deg. C max.
- >Soldering time 3 sec. max.

##### (b) Soldering iron :

- >Temperature of tip 300 deg. C max.
- >Soldering time 3 sec. max.
- >Wattage of iron 40W max.

Before using other soldering conditions than those listed above, please consult with Murata factory representative prior to using. If the soldering conditions are not suitable, e.g., excessive time and/or excessive temperature, the trimmer potentiometer may deviate from the specified characteristics.

- (2) To minimize mechanical stress when adjusting, the trimmer potentiometer should be mounted onto PCB without gap.
- (3) The soldering iron should not come in contact with the case of the trimmer potentiometer. If such contact does occur, the trimmer potentiometer may be damaged.

#### 2. Mounting

- (1) Use PCB hole to meet the pin of the trimmer potentiometer. If the trimmer potentiometer installs into insufficient PCB hole, the

trimmer potentiometer may be damaged by mechanical stress.

- (2) Do not apply excessive force (preferably 9.8N (Ref.; 1kgf) max.), when the trimmer potentiometer is mounted to the PCB.

#### 3. Cleaning

- (1) Isopropyl-alcohol and Ethyl-alcohol are applicable solvents for cleaning. If you use any other types of solvents, please consult with a Murata factory representative prior to using.
- (2) The total cleaning time by cold dipping, vapor and ultrasonic washing (conditions as below) method should be less than 3 minutes.
- (3) For ultra-sonic cleaning, the available condition is as follows.
  - >Power: 600W (67 liter) max.
  - >Frequency: 28kHz
  - >Temperature: Ambient temperature

Due to the ultra-sonic cleaning equipment's peculiar self-resonance point and that the cleaning compatibility usually depends on the jig construction and/or the cleaning condition such as the depth of immersion, please check the cleaning equipment to determine the suitable conditions.

If the trimmer potentiometer is cleaned by other conditions, the trimmer potentiometer may be damaged.

## PV12/PV37/PV23/PV22/PV36 Series Notice

### ■ Notice (Handling)

1. Use suitable screwdrivers that fit comfortably in driver slot. We recommend the screwdrivers below.  
\* Recommended screwdriver for manual adjustment  
ENGINEER INC. : DA-40  
(Murata P/N : KMDR180)  
We can supply the screwdrivers above.  
If you place order, please specify the Murata P/N.
2. Don't apply more than 9.8N (Ref.; 1kgf) of twist and stress after mounting onto PCB to prevent contact intermittence. If excessive force is applied, the trimmer potentiometer may not function.
3. When adjusting with an adjustment tool, the applied force to the adjustment screw should not exceed 4.9N (Ref.; 500gf). If excessive force is applied, the trimmer potentiometer may not function due to damage.
4. When using a lock paint to fix slot position, please use adhesive resin without chlorine or sulfur (Three-bond "1401 series").

### ■ Notice (Other)

1. Please make sure that your product has been evaluated and confirmed against your specifications when our product is mounted to your product.
2. Murata cannot guarantee trimmer potentiometer integrity when used under conditions other than those specified in this document.

## SMD Sealed Type/Lead Sealed Type Specifications and Test Methods


Continued from the preceding page.

| No.         | Item                                                       | Test Methods                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |                           |        |   |   |   |            |                                           |                         |                           |       |             |    |        |    |        |
|-------------|------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------|--------|---|---|---|------------|-------------------------------------------|-------------------------|---------------------------|-------|-------------|----|--------|----|--------|
| 6           | Temperature Cycle                                          | <p>The trimmer potentiometer should be subjected to Table 4 temperature for 5 cycles. The trimmer potentiometer should be removed from the chamber, and maintained at a temperature of 25±5°C for 1~2 hours.</p> <table><tr><th>Sequence</th><th>1</th><th>2</th><th>3</th><th>4</th></tr><tr><td>Temp. (°C)</td><td>PV□□ series<br/>PV22 series<br/>PVF2 series</td><td>-55±3<br/>+25±2<br/>-25±3</td><td>+125±3<br/>+150±3<br/>+60±3</td><td>+25±2</td></tr><tr><td>Time (min.)</td><td>30</td><td>5 max.</td><td>30</td><td>5 max.</td></tr></table> <p>Table 4: One cycle of temperature cycle.</p>                                                                                                                                                                                                                                                                                                                                                 | Sequence                  | 1      | 2 | 3 | 4 | Temp. (°C) | PV□□ series<br>PV22 series<br>PVF2 series | -55±3<br>+25±2<br>-25±3 | +125±3<br>+150±3<br>+60±3 | +25±2 | Time (min.) | 30 | 5 max. | 30 | 5 max. |
| Sequence    | 1                                                          | 2                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | 3                         | 4      |   |   |   |            |                                           |                         |                           |       |             |    |        |    |        |
| Temp. (°C)  | PV□□ series<br>PV22 series<br>PVF2 series                  | -55±3<br>+25±2<br>-25±3                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 | +125±3<br>+150±3<br>+60±3 | +25±2  |   |   |   |            |                                           |                         |                           |       |             |    |        |    |        |
| Time (min.) | 30                                                         | 5 max.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | 30                        | 5 max. |   |   |   |            |                                           |                         |                           |       |             |    |        |    |        |
| 7           | Humidity                                                   | <p>1) PVC6, PV12, PV32, PV34 PVM4A□□□D01 series<br/>The trimmer potentiometer should be placed in a chamber at a temperature of 40±2°C and a humidity of 90~95% without loading for 250±8 hours (500±12 hours for PVM4A□□□D01 series). The trimmer potentiometer should be removed from the chamber, and maintained at a temperature of 25±5°C for 5±1/6 hours.</p> <p>2) PVF2 series<br/>The trimmer potentiometer should be placed in a chamber at 60±2°C and 90~95% without loading for 1000±12 hours. The trimmer potentiometer should be removed from the chamber, and maintained at a temperature of 25±5°C for 5±1/6 hours</p> <p>2) PVG3, PVG5, PV01, PV22, PV23, PV36, PV37 series<br/>The trimmer potentiometer should be subjected Figure-3 the programmed humidity environment for 10 cycle. The trimmer potentiometer should be removed from the chamber, and maintained at a temperature of 25±5°C for 1.5±1/2 hours.</p> <p>Figure 3</p> |                           |        |   |   |   |            |                                           |                         |                           |       |             |    |        |    |        |
| 8           | Vibration                                                  | <p>1) PV□□ series<br/>The trimmer potentiometer should be vibrated throughout the frequency range at the 20G level. A complete frequency range, 10Hz to 2000Hz and back, should be made within 15 minutes for a total of 4 sweeps in each of the three axis direction for a total of 12 sweeps.</p> <p>2) PVF2 series<br/>The trimmer potentiometer should be subjected to vibration at 0.3 inch amplitude. The frequency should be varied uniformly between the approximate limits of 10Hz and 55Hz. This motion should be applied for period of 2 hours in each of 3 mutually perpendicular directions (total of 6 hours).</p>                                                                                                                                                                                                                                                                                                                        |                           |        |   |   |   |            |                                           |                         |                           |       |             |    |        |    |        |
| 9           | Shock                                                      | <p>1) PV□□ series<br/>The trimmer potentiometer should be shocked at the 100G (50G for PV22 and PV23 series) level and should be subjected to 4 shocks in each of the three axis directions for a total of 12 shocks.</p> <p>2) PVM4A□□□D01 series<br/>The trimmer potentiometer should be shocked at the 100G level and should be subjected to 3 shocks in each of the six axis directions for a total of 18 shocks.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |                           |        |   |   |   |            |                                           |                         |                           |       |             |    |        |    |        |
| 10          | Temperature Road Life                                      | <p>Full rated continuous working voltage not exceeding the maximum rated voltage should be applied intermittently between terminal #1 and terminal #3 of the trimmer potentiometer, 1.5 hours on and 0.5 hours off, for a total of 1000±12 hours, at a temperature of 70±2°C (85±2°C for PV01 and PV37 series, 50±2°C for PVF2 series). The trimmer potentiometer should be removed from the chamber, and maintained at a temperature of 25±5°C for 1 to 2 hours.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |                           |        |   |   |   |            |                                           |                         |                           |       |             |    |        |    |        |
| 11          | High Temperature Exposure (Except for PVF2)                | <p>The trimmer potentiometer should be placed in a chamber at a temperature of 125±3°C (150±3°C for PV22 series) 250±8 hours without loading. The trimmer potentiometer should be removed from the chamber, and maintained at a temperature of 25±5°C for 1 to 2 hours.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |                           |        |   |   |   |            |                                           |                         |                           |       |             |    |        |    |        |
| 12          | Low Temperature Exposure (Except for PVF2 and PVM4A□□□D01) | <p>The trimmer potentiometer should be placed in a chamber at a temperature of -55±3°C for 1 hours without loading. Full rated continuous working voltage not exceeding the maximum rated voltage should be applied for 45 minutes. The trimmer potentiometer should be removed from the chamber, and maintained at a temperature of 25±5°C for approximately 24 hours.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |                           |        |   |   |   |            |                                           |                         |                           |       |             |    |        |    |        |



Continued on the following page. ↗

## SMD Sealed Type/Lead Sealed Type Specifications and Test Methods

Continued from the preceding page.

| No. | Item                                                         | Test Methods                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |
|-----|--------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 13  | Low Temperature Operation<br>(Only for PVF2 and PVM4A□□□D01) | The trimmer potentiometer should be placed in a chamber at a temperature of $-25\pm 3^{\circ}\text{C}$ ( $-55\pm 3^{\circ}\text{C}$ for PVM4A□□□D01 series) 48±4 hours without loading. The trimmer potentiometer should be removed from the chamber, and maintained at a temperature of $25\pm 5^{\circ}\text{C}$ for 1-2 hours                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
| 14  | Rotational Life                                              | <p>1) PV□□ series<br/>Full rated continuous working voltage not exceeding the maximum rated voltage should be applied with the circuit shown in the figure. The adjustment rotor (screw) should be continuously cycled through not less than 90% of effective-electrical rotational angle (number of turns), at the rate of 1 cycle for 5 seconds minimum to 2.5 minutes maximum for total of 200 cycles.</p>  <p>Figure 4</p> <p>2) PVG3, PVG5 series<br/>The adjustment rotor (screw) should be continuously cycled though not less than 90% of effective-electrical rotational angle (number of turns), at the rate of 1 cycle for 5 seconds minimum to 2.5 minutes maximum for a total of 50 (100 for PVG5) cycles, without loading.</p> <p>3) PVF2, PVM4A□□□D01 series<br/>The wiper should be rotated over 90% of the effective rotational angle without loading at a speed of 10 cycles per minute, for 100 cycles continuously.</p> |

## Angle Sensing Potentiometer Specifications and Test Methods


| No.                              | Item                                  | Test Methods                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |             |             |   |    |   |                                  |             |             |             |             |             |    |        |    |        |
|----------------------------------|---------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|-------------|---|----|---|----------------------------------|-------------|-------------|-------------|-------------|-------------|----|--------|----|--------|
| 1                                | Linearity                             | <p>Independent linearity should vary no more than <math>\pm 2\%</math> within <math>\pm 160^\circ</math> to 50% voltage ratio.<br/>Taper : linear, 100%/333.3° Measured with the circuit as below (Figure 1).</p> <div><div><p>Output voltage ratio (%)</p><math display="block">\left( \frac{V(1-2)}{V(1-3)} \times 100 \right)</math></div><div></div></div> <p>Figure-1</p>                                                                                                                                                                                                                                                                                        |             |             |   |    |   |                                  |             |             |             |             |             |    |        |    |        |
| 2                                | Temperature Coefficient of Resistance | <p>The rotary position sensor should be subjected to each of the following temperatures (see Table 1) for 30-45 minutes.<br/>Temperature coefficient of resistance should be applied to the following formula.</p> $TCR = \frac{R_2 - R_1}{R_1 (t_2 - t_1)} \times 10^6 \text{ (ppm/}^\circ\text{C)}$ <p><math>t_1</math> : Reference temperature in degrees celsius<br/><math>t_2</math> : Test temperature in degrees celsius<br/><math>R_1</math> : Resistance at reference temperature in ohm<br/><math>R_2</math> : Resistance at test temperature in ohm</p> <table><tr><th>Sequence</th><th>*1</th><th>2</th><th>*3</th><th>4</th></tr><tr><td>Temperature (<math>^\circ\text{C}</math>)</td><td>+25</td><td>-40</td><td>+25</td><td>+85</td></tr></table> <p>Note * : Reference temperature</p> <p>Table-1 Test temperatures</p> | Sequence    | *1          | 2 | *3 | 4 | Temperature ( $^\circ\text{C}$ ) | +25         | -40         | +25         | +85         |             |    |        |    |        |
| Sequence                         | *1                                    | 2                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | *3          | 4           |   |    |   |                                  |             |             |             |             |             |    |        |    |        |
| Temperature ( $^\circ\text{C}$ ) | +25                                   | -40                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | +25         | +85         |   |    |   |                                  |             |             |             |             |             |    |        |    |        |
| 3                                | Temperature Cycle (Thermal Shock)     | <p>The rotary position sensor should be subjected to Table 2 temperature for 5 cycles.<br/>Then, the rotary position sensor should be kept in the dry box for 24 +8/-0 hrs.</p> <table><tr><th>Sequence</th><th>1</th><th>2</th><th>3</th><th>4</th></tr><tr><td>Temperature (<math>^\circ\text{C}</math>)</td><td>-40<math>\pm 3</math></td><td>+25<math>\pm 2</math></td><td>+85<math>\pm 3</math></td><td>+25<math>\pm 2</math></td></tr><tr><td>Time (min.)</td><td>30</td><td>5 max.</td><td>30</td><td>5 max.</td></tr></table> <p>Table 2: One cycle of temperature cycle</p>                                                                                                                                                                                                                                                     | Sequence    | 1           | 2 | 3  | 4 | Temperature ( $^\circ\text{C}$ ) | -40 $\pm 3$ | +25 $\pm 2$ | +85 $\pm 3$ | +25 $\pm 2$ | Time (min.) | 30 | 5 max. | 30 | 5 max. |
| Sequence                         | 1                                     | 2                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | 3           | 4           |   |    |   |                                  |             |             |             |             |             |    |        |    |        |
| Temperature ( $^\circ\text{C}$ ) | -40 $\pm 3$                           | +25 $\pm 2$                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | +85 $\pm 3$ | +25 $\pm 2$ |   |    |   |                                  |             |             |             |             |             |    |        |    |        |
| Time (min.)                      | 30                                    | 5 max.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | 30          | 5 max.      |   |    |   |                                  |             |             |             |             |             |    |        |    |        |
| 4                                | Humidity                              | <p>The rotary position sensor should be stored in a chamber at temperature of +60<math>\pm 2^\circ\text{C}</math> and relative Humidity of 90-95% for 250<math>\pm 8</math> hrs. After removing from the chamber, the rotary position sensor should be kept in the dry box for 24 +8/-0 hours.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |             |             |   |    |   |                                  |             |             |             |             |             |    |        |    |        |
| 5                                | Vibration                             | <p>The rotary position sensor should be tested under the condition of the amplitude of 1.5mm, the frequency range from 10 to 55Hz (should be traversed in approximately one minute) and 2 hours in each of 3 mutually perpendicular directions (total 6 hours). Then, the rotary position sensor should be kept in the dry box for 1-2 hrs.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |             |             |   |    |   |                                  |             |             |             |             |             |    |        |    |        |
| 6                                | Shock                                 | <p>The rotary position sensor should be tested under the condition of the peak acceleration 20G max. in half-sine wave and 5 shocks in each of 3 mutually perpendicular directions (total 15 shocks). Then, the rotary position sensor should be kept in the dry box for 1-2 hrs.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |             |             |   |    |   |                                  |             |             |             |             |             |    |        |    |        |
| 7                                | Humidity Load Life                    | <p>Full rated continuous working voltage not exceeding 5Vdc should be applied intermittently between terminal #1 and terminal #3 of the rotary position sensor, 1.5 hours on and 0.5 hours off, for 96<math>\pm 4</math> hours in total in a chamber at a temperature of +40<math>\pm 2^\circ\text{C}</math> and relative humidity of 90-95%. After removing from the chamber, the rotary position sensor should be kept in the dry box for 24 +8/-0 hours.</p>                                                                                                                                                                                                                                                                                                                                                                          |             |             |   |    |   |                                  |             |             |             |             |             |    |        |    |        |
| 8                                | High Temp. Exposure                   | <p>The rotary position sensor should be stored in a chamber at the temperature of +85<math>\pm 3^\circ\text{C}</math> without loading for 250<math>\pm 8</math> hours. After removing from the chamber, the rotary position sensor should be kept in the dry box for 24 +8/-0 hours.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |             |             |   |    |   |                                  |             |             |             |             |             |    |        |    |        |
| 9                                | Low Temp. Exposure                    | <p>The rotary position sensor should be stored in a chamber at the temperature of -40<math>\pm 3^\circ\text{C}</math> without loading for 168<math>\pm 4</math> hours. After removing from the chamber, the rotary position sensor should be kept in the dry box for 24 +8/-0 hours.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |             |             |   |    |   |                                  |             |             |             |             |             |    |        |    |        |
| 10                               | Rotational Life                       | <p>The adjustment rotor should be continuously rotated within <math>\pm 160^\circ</math> of effective electrical rotational angle, at the rate of one cycle for 6 seconds for 1 Million cycles under the condition of +25<math>\pm 2^\circ\text{C}</math> of temperature without loading.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |             |             |   |    |   |                                  |             |             |             |             |             |    |        |    |        |

## Packaging

### ■ Minimum Quantity

| Part Number   | Minimum Quantity (pcs.) |             |           |          |      |      |
|---------------|-------------------------|-------------|-----------|----------|------|------|
|               | ø180mm reel             | ø330mm reel | Ammo Pack | Magazine | Bulk | Tray |
| PVZ2A         | 3000                    | 12000       | —         | —        | 1000 | —    |
| PVZ2K         | 3000                    | —           | —         | —        | 1000 | —    |
| PVZ3A         | 2000                    | 8000        | —         | —        | 1000 | —    |
| PVZ3K/R       | 1500                    | —           | —         | —        | 1000 | —    |
| PVS3          | 2500                    | 8000        | —         | —        | 500  | —    |
| PVA3          | 2000                    | 8000        | —         | —        | 500  | —    |
| PVG3A/G       | 1000                    | —           | —         | —        | 500  | —    |
| PVG3K         | 500                     | —           | —         | —        | —    | —    |
| PVM4          | 500                     | 3000        | —         | —        | 500  | —    |
| PVF2A         | 500                     | —           | —         | —        | 100  | —    |
| PVG5A         | 250                     | —           | —         | —        | 50   | —    |
| PVG5H         | 500                     | —           | —         | —        | 50   | —    |
| PV01W         | —                       | —           | —         | 50       | —    | —    |
| PV01P         | —                       | —           | —         | 50       | —    | —    |
| PV01X         | —                       | —           | —         | 50       | —    | —    |
| PVC6A/D/G/H/E | —                       | —           | —         | 50       | 50   | —    |
| PVC6M/Q       | —                       | —           | 1000      | 50       | 50   | —    |
| PV34          | —                       | —           | —         | —        | 100  | —    |
| PV32          | —                       | —           | —         | —        | 100  | —    |
| PV23/12       | —                       | —           | —         | —        | 50   | —    |
| PV22          | —                       | —           | —         | —        | 30   | —    |
| PV36W         | —                       | —           | 1000      | 50       | 50   | —    |
| PV36Y         | —                       | —           | —         | 50       | 50   | —    |
| PV36X         | —                       | —           | 1000      | 40       | 50   | —    |
| PV36Z/P       | —                       | —           | —         | 40       | 50   | —    |
| PV37Y/Z       | —                       | —           | 1000      | —        | 50   | —    |
| PV37W/X/P     | —                       | —           | —         | —        | 50   | —    |
| PVS1A         | —                       | 1000        | —         | —        | 50   | —    |
| PVS1L         | —                       | —           | —         | —        | —    | 1000 |

### ■ Dimensions of Reel



\* 10.0±1.5 ( 8mm Width) — PVZ2A, PVZ3A, PVS3, PVA3, PVF2  
 14.0±1.5 (12mm Width) — PVG5H, PVG3, PVZ2K, PVZ3K, PVZ3R, PVM4  
 17.0±1.5 (16mm Width) — PVG5A

(in mm)


Continued on the following page. ↗

## Packaging

Continued from the preceding page.


### ■ Dimensions of Plastic Tape

PVG3K



(in mm)

PVS1




(in mm)  
(Tolerance:  $\pm 0.1$ )

### ■ Dimensions of Radial Taping

PVC6M


0.55W $\times$ 3.2L $\times$ 1.3D



(in mm)  
(Tolerance:  $\pm 0.3$ )


PVC6Q

0.55W $\times$ 3.2L $\times$ 1.3D




(in mm)  
(Tolerance:  $\pm 0.3$ )

PV37Y



(in mm)  
(Tolerance:  $\pm 0.3$ )

PV37Z





(in mm)  
(Tolerance:  $\pm 0.3$ )

Continued on the following page. ➤


## Packaging

Continued from the preceding page.

### ■ Dimensions of Radial Taping




### ■ Dimensions of Ammo Pack




### ■ Dimensions of Magazine Packaging


**PV01**




**PVC6**



**PV36W/Y/X/Z**



**PV36P**



(in mm)

## Recommended Adjustment Tools/Qualified Standards

### ■ Recommended Adjustment Tools

| Trimmer Potentiometer Series | Manufacturers          | Model Number   | MURATA Model Number | Blade                |
|------------------------------|------------------------|----------------|---------------------|----------------------|
| <b>PVZ2</b>                  | MURATA MFG.            | KMDR090        | KMDR090             | – Minus (round edge) |
| <b>PVZ2A_A04</b>             | VESSEL MFG.            | No.9000+0X30   | KMDR150             | + Cross              |
| <b>PVZ3</b>                  | VESSEL MFG.            | No.9000+1.7X30 | KMDR080             | + Cross              |
|                              | TORAY INDUSTRIES, INC. | SA-2225        | KMDR070             | – Minus (round edge) |
| <b>PVA3</b>                  | VESSEL MFG.            | No.9000+1.7X30 | KMDR080             | + Cross              |
|                              | TORAY INDUSTRIES, INC. | SA-2225        | KMDR070             | – Minus (round edge) |
| <b>PVS3</b>                  | TORAY INDUSTRIES, INC. | SA-2225        | KMDR070             | – Minus (round edge) |
| <b>PVG3</b>                  | TORAY INDUSTRIES, INC. | SA-2225        | KMDR070             | – Minus (round edge) |
| <b>PVM4</b>                  | VESSEL MFG.            | No.9000–2.6X30 | KMDR120             | – Minus              |
| <b>PVG5</b>                  | VESSEL MFG.            | No.9000–1.3X30 | KMDR130             | – Minus              |
|                              | ENGINEER INC.          | DA-54          |                     | – Minus              |
| <b>PVC6</b>                  | VESSEL MFG.            | No.9000+0X30   | KMDR150             | + Cross              |
|                              | TORAY INDUSTRIES, INC. | SA-2225        | KMDR070             | – Minus (round edge) |
| others                       | VESSEL MFG.            | No.9000–1.8X30 | KMDR110             | – Minus              |
|                              | ENGINEER INC.          | DA-40          | KMDR180             | – Minus (both ends)  |
|                              |                        | DA-55          |                     | – Minus              |

### ■ For Automatic Adjustment

| Trimmer Potentiometer Series                             | Manufacturers          | Model Number | MURATA Model Number | Blade                |
|----------------------------------------------------------|------------------------|--------------|---------------------|----------------------|
| <b>PVZ3</b><br><b>PVA3</b><br><b>PVS3</b><br><b>PVG3</b> | TORAY INDUSTRIES, INC. | JB-2225      | KMBT070             | – Minus (round edge) |
| <b>PVC6</b>                                              | VESSEL MFG.            | No.CA-10     | KMBT090             | + Cross              |
|                                                          | TORAY INDUSTRIES, INC. | JB-2225      | KMBT070             | – Minus (round edge) |

### ■ Qualified Standards

The products listed here have been produced by the QS9000 and ISO9001 certified factory.

| MURATA FACTORY                  | Qualified Date  | Standard                       | Qualified Number |
|---------------------------------|-----------------|--------------------------------|------------------|
| Sabae Murata Mfg.Co.,Ltd.       | August 14, 1997 | UNDERWRITERS LABORATORIES INC. | A5704            |
| Wuxi Murata Electronis Co.,Ltd. | May 12, 1999    | UNDERWRITERS LABORATORIES INC. | A7924            |

\* No ODCs (Ozone Depleting Chemicals) are used on all Murata's trimmer potentiometers.

⚠Note:

1. Export Control

〈For customers outside Japan〉

Murata products should not be used or sold for use in the development, production, stockpiling or utilization of any conventional weapons or mass-destructive weapons (nuclear weapons, chemical or biological weapons, or missiles), or any other weapons.

〈For customers in Japan〉

For products which are controlled items subject to the "Foreign Exchange and Foreign Trade Law" of Japan, the export license specified by the law is required for export.

2. Please contact our sales representatives or product engineers before using the products in this catalog for the applications listed below, which require especially high reliability for the prevention of defects which might directly damage to a third party's life, body or property, or when one of our products is intended for use in applications other than those specified in this catalog.

- |                             |                                                                                                             |
|-----------------------------|-------------------------------------------------------------------------------------------------------------|
| ① Aircraft equipment        | ② Aerospace equipment                                                                                       |
| ③ Undersea equipment        | ④ Power plant equipment                                                                                     |
| ⑤ Medical equipment         | ⑥ Transportation equipment (vehicles, trains, ships, etc.)                                                  |
| ⑦ Traffic signal equipment  | ⑧ Disaster prevention / crime prevention equipment                                                          |
| ⑨ Data-processing equipment | ⑩ Application of similar complexity and/or reliability requirements to the applications listed in the above |

3. Product specifications in this catalog are as of April 2004. They are subject to change or our products in it may be discontinued without advance notice. Please check with our sales representatives or product engineers before ordering. If there are any questions, please contact our sales representatives or product engineers.

4. Please read rating and ⚠CAUTION (for storage, operating, rating, soldering, mounting and handling) in this catalog to prevent smoking and/or burning, etc.

5. This catalog has only typical specifications because there is no space for detailed specifications. Therefore, please approve our product specifications or transact the approval sheet for product specifications before ordering.

6. Please note that unless otherwise specified, we shall assume no responsibility whatsoever for any conflict or dispute that may occur in connection with the effect of our and/or a third party's intellectual property rights and other related rights in consideration of your use of our products and/or information described or contained in our catalogs. In this connection, no representation shall be made to the effect that any third parties are authorized to use the rights mentioned above under licenses without our consent.

7. No ozone depleting substances (ODS) under the Montreal Protocol are used in our manufacturing process.