



GP1A047RDZLF

Product Change Notifications

Type	File Name	Revision Date	Size
PCN	PCN-2011-0406-02.pdf Sharp is discontinuing the above parts. No last buy opportunity is being offered. GP2S60 is the suggested alternative only for GP2L24ABJ00F, GP2L24BCJ00F, and GP2S24ABJ00F. It is a functional replacement only.	04/05/2011	62.85 KB
PCN	PCN-01302009-1.pdf Photointerrupters in the series GP1A, GP1L, GP1S, GP2S, GP3A, and GP3S: Packing Change. Beginning in March 2009, the photointerrupters in the above series will be sealed in their packing bags with tape. There is no effect upon optical, reliability, quality, mechanical, electrical, or RoHS specifications.	01/30/2009	85.15 KB
PCN	PCN-200601013.pdf For various optoelectronic components please see the document for the full list. Suggested replacement parts: Please see the document for the full list.	10/13/2006	30.1 KB

Documentation

There are no matching documents for this product or criteria.

Can't find the document you are looking for? Please contact your local [Sharp Microelectronics representative](#) for assistance.

Family:	GP1A047RDZLF
Output Signal:	OPIC
RoHS:	Yes
Slit Width:	0.0847 mm
Status:	Discontinued
Type:	Transmissive