


Connectors for control signals

CM-series

HiPower



Type		Number of poles	Description	Order no.
		6 + PE	Cable socket, straight design, strain relief by means of a clamp Operating voltage: 10 A	932 460-100
		7	Cable socket, straight design, strain relief by means of a clamping cage Operating current: 16 A	933 052-100
		8	Cable socket, straight design, strain relief by means of a clamping cage Operating current: 10 A	932 842-100
		14	Cable socket, straight design, strain relief by means of a clamping cage Operating current: 5 A	933 067-100
		17	Cable socket, straight design, strain relief by means of a clamping cage Operating current: 4 A	933 068-100