


Exploded view diagram of a mechanical assembly. The diagram shows various components and their assembly sequence, indicated by numbered callouts (1 through 63). Key components include a motor unit (37), a terminal support (34), a main housing (44), and various mounting brackets and fasteners. A detail view of the terminal support location shows a dimension of 3.56 ± 0.5 [1.40 ± 0.20] and labels REF (8) and REF (34).

- * WARNING
ON INSTALLATION, SET WIRE
DISC TO LARGEST WIRE SIZE
SETTING. USE OF SETTINGS
BELOW MIN. REQUIRED CRIMP
HEIGHT SETTING WILL CAUSE
DAMAGE TO CRIMP TOOLING.



THIS IS A STANDARD DRAFTING TEMPLATE FOR INFORMATION ONLY. NO INFORMATION SHOULD BE CONTAINED HEREIN FOR THE LATEST VERSION.		DWG: 08-Mar-06 LHOFFSHOE CIR:		 Tyco Electronics Harrisburg, PA 17105-3608	
DIMENSIONS: mm [IN]		TOLERANCES UNLESS OTHERWISE SPECIFIED: 0. PLC ±.1 1. PLC ±.1 2. PLC ±.1 3. PLC ±.1 4. PLC ±.1 ANGLES ±.1		APD: 08-Mar-06 M. CLIFFORD PRODUCT SPEC APPLICATION SPEC See Table REIGHT:	
MATERIAL: -		FINISH: -		NAME: FINE ADJUST SIDE FEED HDI APPLICATOR SIZE: A CABLE CODE: 00779 DRAWING NO: C=1528603 RESTRICTED TO:	
CUSTOMER DRAWING		SCALE: 3:5		SHEET 1 OF 1 REV A	