



POWER CONTACTS

Process

A Contact pull out




B New contact insertion




POWER CONTACTS (by front face)

Process

A Contact pull out




B New contact insertion



* SETTING METHOD


Unscrew the cap of the tool to change the center punch.



KIT CONTENTS:

IT.	Designation	Part-number	Reference mark
1	Automatic punch	8607-3124	
2	Center punch (contact pull out)	8626-5244	EP
3	Center punch (new contact insertion)	8626-5245	RP
4	Pliers	8626-5248	
5	Tool case	8646-3062-A	
6	Wedging foam	8626-5249	

KIT PRESENTATION



Part number	HM1-5247 (POWER CONTACTS)		
d	02/07/97	Modify part-number.8626-5247 --> HM1-5247.	--
ISS	DATE	Latest modification by : LELEON	MOD N°
Designed by: LELEON date:18/04/97		Type of drawing: CLIENT	SHEET 1/1
TITLE : DIRECTIONS FOR USE OF HM1 MALE INDIVIDUAL PRESS-FIT REMOVAL KIT.			
SCALE: 1			
	FRAMATOME CONNECTORS FRANCE Rue Louis Breguet - BP 05 72024 LE MANS Cedex Tel. (33)02.43.78.34.00		This document is the property of FRAMATOME CONNECTORS FRANCE It must not be reproduced or communicated without permission in writing from the owners
	FORMAT A3	DRG N° C-8626-1034	