



**Product Number: 3057**

**3M™ Stand-By Jack**



3M™ Monitor Stand-By Jack 3057 allows an operator to disconnect a ground cord from the wrist band and leave the workstation without deactivating the workstation monitor.

When personnel leave the workstation they simply detach the cord from the wrist band and plug it into the 3057. When the jack is grounded, the green light will illuminate and the yellow "Caution" lamp will slowly flash .

3M Id : 98-0798-2446-6