

THIS COPY IS PROVIDED ON A RESTRICTED BASIS AND IS NOT TO BE USED IN ANY WAY DETRIMENTAL TO THE INTERESTS OF PANDUIT CORP.

2.125 ±.062
[54.0 ±1.6]



A LIFE IS ON THE LINE!
OSHA LOCKOUT STEPS
SHUTDOWN

Inform operator and supervisor about work
to be done

- 1) Prepare for shutdown
- 2) Shutdown/turn off equipment
- 3) Isolate from energy source
- 4) Apply lockout/tagout to energy isolating device
- 5) Release all potentially hazardous stored or residual energy
- 6) Verify the isolation

STARTUP

- 1) Assure equipment operationally intact, clear all personnel & tools
- 2) Ensure employee are safety positioned
- 3) Assure lockout/tagout is removed from each energy-isolating device
- 4) Notify affected employees of lockout/tagout removal and that work has been completed
(See section 6(e) and 6(f) of 29 CFR 1910.147 for specific requirements of the standard)

FRONT

.125 R
TYP. 4 PLCS.

RED

BLACK

WHITE

BLACK



NOTES:

1. MILLIMETERS ARE IN [].
5. QUANTITY PER PKG. IS 25.

2012	S	M	T	W	T	F	S	2012	S	M	T	W	T	F	S
JAN	1	2	3	4	5	6	7	JUL	1	2	3	4	5	6	7
	8	9	10	11	12	13	14		8	9	10	11	12	13	14
	15	16	17	18	19	20	21		15	16	17	18	19	20	21
	22	23	24	25	26	27	28		22	23	24	25	26	27	28
	29	30	31						29	30	31				
FEB	5	6	7	8	9	10	11	AUG	5	6	7	8	9	10	11
	12	13	14	15	16	17	18		12	13	14	15	16	17	18
	19	20	21	22	23	24	25		19	20	21	22	23	24	25
	26	27	28	29					26	27	28	29	30	31	
MAR	4	5	6	7	8	9	10	SEP	2	3	4	5	6	7	8
	11	12	13	14	15	16	17		9	10	11	12	13	14	15
	18	19	20	21	22	23	24		16	17	18	19	20	21	22
	25	26	27	28	29	30	31		23	24	25	26	27	28	29
									30						
APR	1	2	3	4	5	6	7	OCT	1	2	3	4	5	6	
	8	9	10	11	12	13	14		7	8	9	10	11	12	13
	15	16	17	18	19	20	21		14	15	16	17	18	19	20
	22	23	24	25	26	27	28		21	22	23	24	25	26	27
	29	30							28	29	30	31			
MAY	6	7	8	9	10	11	12	NOV	4	5	6	7	8	9	10
	13	14	15	16	17	18	19		11	12	13	14	15	16	17
	20	21	22	23	24	25	26		18	19	20	21	22	23	24
	27	28	29	30	31				25	26	27	28	29	30	
JUN	3	4	5	6	7	8	9	DEC	2	3	4	5	6	7	8
	10	11	12	13	14	15	16		9	10	11	12	13	14	15
	17	18	19	20	21	22	23		16	17	18	19	20	21	22
	24	25	26	27	28	29	30		23	24	25	26	27	28	29
									30	31					



Lockout/Tagout Products

888-506-5400

PSL-STEPS

BACK

3.375 ±.062
[85.7 ±1.6]

CAD FILENAME/LAYERS

100360BG-DC-C10815/03C

PANDUIT CORP. TINLEY PARK, ILLINOIS

PSL-STEPS SAFETY SIGN

UNLESS OTHERWISE SPECIFIED,
DIMENSIONAL TOLERANCES ARE:
(.X) ± .12 (.XXX) ± .025
(.XX) ± .062 ANGLES ±

UNLESS OTHERWISE SPECIFIED,
ALL DIMENSIONS ARE GIVEN
IN INCHES, THIRD ANGLE PROJECTION.

DRAWN BY
RVU

MAT'L:

SCALE NTS

DATE
1/5/10

GMRV10
VINYL CLOTH

DRAWING NO.
C10815

DWG
A
SIZE

CHK'D

M. A.

REV	DATE	BY	CHK	DESCRIPTION	ECN	R	CUST	SUP
2	9/19/11	RVU		UPDATE YEAR 2012 AND DAYS, MONTHS, AND WEEKS.	6515	R		
1	11/1/10	RVU		UPDATE YEAR 2011 AND DAYS, MONTHS, AND WEEKS.	6140	R		
0	1/5/10	RVU		DRAWING RELEASE.	5939	R		