




REV	DESCRIPTION	DATE
A	RELEASE	8/4/08
B	OBSOLETE SUPERSEDED BY 99-7821CX	06/14/13



50 1920	3	SET SCREW	9
50 1736	1	SET SCREW	8
128966	1	PULLER, COLAR CUTTER	7
128964	1	ANVIL, COLLAR CUTTER ASSY	6
128967	1	SLEEVE	5
50 20 17	4	SSCR #10-32 X 3/16	4
128677	1	PIN	3
508319	1	SPRING	2
128968	1	ANVIL HOLDER, COLLAR CUTTER	1
PART NO.	QTY	DESCRIPTION	ITEM

IDENTIFICATION PER SPEC 42-311: ★ PERMANENT			
ITAR:		HUCK INTERNATIONAL, INC., I.S.D. 1 CORPORATE DR, P.O. BOX 2270 KINGSTON, NEW YORK 12401	
ECCN: EAR99		ASSY, COLLAR CUTTER BTT35LS	
SCH B#: 8467.99.0190		DET: TRK	CK: DATE: 8/4/08 SCALE: 1:1
HTS: 8467.99.0190		B	99-7821CC

- NOTES:
- 1 PRESS DOWEL PIN 128677 FLUSH TO .010 BELOW O.D. SURFACE OF SLEEVE 128967.
 - 2 APPLY ANTI-SEIZE LUBRICANT P/N: 508183 TO OUTSIDE OF PULLER AND INSIDE OF ANVIL.
 - 3 APPLY VIBRA-TITE P/N: 505125 TO SET SCREW THREADS PER MFR'S INSTRUCTIONS.
 - 4 APPLY WARNING STICKER P/N: 590273 TO ANVIL HOLDER. DO NOT PERMIT STICKER TO OVERLAP ONTO ANVIL