

Distributed by:

JAMECO[®]
ELECTRONICS

www.Jameco.com ♦ 1-800-831-4242

The content and copyrights of the attached
material are the property of its owner.

Jameco Part Number 1972987

- [Home](#)
- [Part Number Search](#)
- [Document Search](#)
- [CAD Model Search](#)
- [Text Search](#)
- [Alternate/Lead Free Part Search](#)
- [Multiple Part Comparison](#)
- [Alphabetical Search](#)
- [Brand Search](#)
- [Industry Product Search](#)
- [Product Type Search](#)
- [Product Family Search](#)
- [Competitor Cross Reference](#)
- [Lead Free Solutions](#)
- [Tool Search](#)
- [Help/Glossary](#)

☐ DIP Sockets

 RoHS Compliant RoHS Compliant

Search for Parts

Related Part Information		
General Information	eCommerce	Related Part Information
 General Info  Sales Info	 Pricing	 Tooling
 Assembly Subcontractors	 Product Availability	

Product Photo

Other Properties:	
RoHS/ELV Compliance History:	Always was compliant
Insulation Resistance (MΩ):	5,000
Contact Resistance (mΩ):	10
Sleeve Material:	Brass/Copper
Contact Termination Area Plating:	Gold
Product Series:	500 Series

Contact Mating Area Plating:	Gold (25)
Contact Style:	Screw Machine
Mating Contact Type:	Four-Fingered
Height Above PC Board (mm [in]):	4.57 [0.180]
Temperature Range (°C):	125
Packaging Method:	Tube
Termination Post Length (mm [in]):	3.18 [0.125]

[Copyright](#) and [Privacy Statement](#)

Visit [Tyco International Ltd.](#)

[Products](#) | [Catalog](#) | [Brands](#) | [Industries](#) | [Commerce](#) | [Supplier](#) | [Contact Us](#) | [About](#) | [Home](#)

i2 Technologies US, Inc.

HTML Pages converted to PDF Document

This document contain component information from the manufacturer's website which are not available in a revision controlled document from the manufacturer. To facilitate the addition of these parts into the Electronics Database, we are converting the HTML pages related to that part, from the manufacturer's website into Adobe PDF format. The contents of this document is based on the information provided on the manufacturer's website, therefore the information may have been changed by the manufacturer since this was created.

