

Product Update Memo

TRIMMING POTENTIOMETERS

August, 2006

Bourns Manufacturers Representatives
Corporate Distributor Product Managers
Americas Sales Team
Asia Sales Team
Europe Sales Team
Bourns Internal
Bourns Plant Managers

Product Discontinuation of Models **3318PSGB, TC34, TC86 and TC89**

Bourns® Trimpot® Division is discontinuing Models 3318PSGB, TC34, TC86 and TC89. The recommended replacements for each model are below.

Obsolete	Replacement
3318P	3318F
3318S	3318K
3318B	No Replacement
3318G(A)	3318F(A)
3318S(A)	3318K(A)
3318B(A)	No Replacement
TC34R	No Replacement
TC86P	3306P
TC86F	3306F
TC86W	3306W
TC86K	3306K
TC89P	3309P
TC89W	3309W

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

Bourns:

[TC89W-1-103](#)