



# GP2A201LCSAF

## Distributor Inventory

Part Number	Distributor	Quantity	Inv. Date
GP2A201LCSAF	<a href="#">DIGI-KEY CORPORATION</a>	0	2/26/2015

## Product Change Notifications

Type	File Name	Revision Date	Size
PCN	<a href="#">PCN-2011-0406-02.pdf</a> Sharp is discontinuing the above parts. No last buy opportunity is being offered. GP2S60 is the suggested alternative only for GP2L24ABJ00F, GP2L24BCJ00F, and GP2S24ABJ00F. It is a functional replacement only.	04/05/2011	62.85 KB
PCN	<a href="#">PCN-20070504-01.pdf</a> Photointerrupters:Internal Chip Change. The infrared emitter chips used in the listed Sharp devices will be changed to allow for a more stable source of supply. This change will take place as a running change to production beginning in June, 2007.	05/04/2007	30.45 KB

## Documentation

*There are no matching documents for this product or criteria.*

Can't find the document you are looking for? Please contact your local [Sharp Microelectronics representative](#) for assistance.

Description:	Photointerrupter right angle part 1.65mm Gap
Family:	GP2A201LCSAF
Output Signal:	OPIC
RoHS:	Yes
Status:	Discontinued
Suggested Alternative Part Number:	none
Type:	Reflective