

## Update Notification Document #: FPCN20989X1

Issue Date: 23 October 2015

Title of Change:	Update to SQFP48 & SQFP64 Package Small Tray Products change in Minimum Order Quantity (MOQ)					
Proposed first ship date:	27 November 2015	nber 2015				
Contact information:	nation: Contact your local ON Semiconductor Sales Office or <takeshi2.hoshino@onsemi.com> <hiroshi2.kobayashi@onsemi.com></hiroshi2.kobayashi@onsemi.com></takeshi2.hoshino@onsemi.com>					
Samples:	Contact your local ON Semiconductor Sales Office					
Additional Reliability Data:	Contact your local ON Semiconductor Sales Office					
Type of notification:	ON Semiconductor will consider this change accepted, unless an inquiry is made in writing within 30 days of delivery of this notice. To do so, contact <pcn.support@onsemi.com>.</pcn.support@onsemi.com>					
Change category:	☐ Wafer Fab Change ☐ Assembly Change	☐ Test Change ☐ Other packing method				
Change Sub-Category(s):  ☐ Manufacturing Site Change/Addition ☐ Material Change ☐ Product specific change		<ul><li>□ Datasheet/Product Doc change</li><li>□ Shipping/Packaging/Marking</li><li>□ Other: packing method</li></ul>				
Sites Affected:  All site(s) not ap	plicable	☐ External Foundry/Subcon site(s)				
Description and Purpose:						
This UN is issued to inform customers of the following changes on FPCN20989 series:  • List of Contact persons for FPCN20989 series will now be just: Takeshi2.Hoshino@onsemi.com and Hiroshi2.Kobayashi@onsemi.com						

- MOQ information corrections:

MOQ :OLD Packing method		MOQ:NEW Packing method		
	500 pcs(50pcs/trayx10trays)	1250pcs(250pcs/trayx5trays)		

The change in Minimum Packing Quantity (MPQ) will be implemented. The dimensions of the tray will be large as well as the packing material.

Please see the difference between attached detailed documents of MOQ before and after change.





To access file attachments on pdf copy of PCN, please be guided by the steps below:

- 1. Download pdf copy of the PCN to your computer
- 2. Open the downloaded pdf copy of the PCN
- 3. Click on the paper clip icon available on the menu provided in the left/bottom portion of the screen to reveal the Attachment field
- 4. Then click on the attached file/s

TEM001153 Rev. C Page 1 of 2



## Update Notification Document #: FPCN20989X1

Issue Date: 23 October 2015

## **List of Affected Standard Parts:**

Part Number	Qualification Vehicle
LC75411WS-E	
LC75411WS-UF-E	
LC75833WHS-E	
LC75834WHS-E	
LC75835W-E	
LC75836W-E	
LC75836WH-E	LC75836WS-E
LC75836WS-E	
LC75836WS-T-E	
LC75841PE-H	
LC75841PES-H	
LC75863W-E	
LC75863WS-E	

TEM001153 Rev. C Page 2 of 2



If no Customer Part Number is on file, the CPN Part Number is marked "CPN Unassigned".

MPN	CPN	Company Name	Company Code	Division Name	Division Code
LC75836WH-E	CPN Unassigned	ebv elektronik	ekEBV	ELEKTRONIK GMBH & CO	EXATZ
				KG	
LC75836WH-E	CPN Unassigned	ebv elektronik	ek	EBV ELEKTRONIK GMBH	EVBKZ