

4

This diagram shows the exploded view of a mechanical assembly. The central component is a square housing with a large circular opening in the center and two smaller rectangular slots on the top and bottom edges. To the left is a cylindrical pin with a flange. To the right are two circular flanges, one with a central hole and one with a central slot. Further to the right is a hexagonal nut.

R	8-9-06	JsP	<i>MAO</i>	RELEASED TO PRODUCTION	02479-367	<i>MAO</i>	<i>MAO</i>		
REV	DATE	BY	CHK	DESCRIPTION	ECN - R	CUST	SUP	OTH	