



|                                                                                                                                         |  |
|-----------------------------------------------------------------------------------------------------------------------------------------|--|
| Complete magnetic bases                                                                                                                 |  |
| Solid holding of precision measuring equipment.                                                                                         |  |
|                                                                                                                                         |  |
| For use in the measurement, inspection and positioning of workpieces with dial indicators.                                              |  |
|                                                                                                                                         |  |
| To measure the flatness of a workpiece after grinding or milling.                                                                       |  |
|                                                                                                                                         |  |
| For checking concentricity of a workpiece. All stands will clamp onto curved and flat surfaces, with the exception of E909 (flat only). |  |
|                                                                                                                                         |  |

| <b>Product</b> |                      |                       |                         |                                 |             |
|----------------|----------------------|-----------------------|-------------------------|---------------------------------|-------------|
| <b>No.</b>     | <b>Base Part No.</b> | <b>Switching type</b> | <b>Fitment Part No.</b> | <b>Fitment type</b>             | <b>Hold</b> |
|                |                      |                       |                         |                                 | kg          |
| E901           | E901WF               | Push button           | RP991BL                 | Heavy duty with fine adjustment | 80          |
| E901/1         | E901WF               | Push button           | RP901/1                 | Extra large heavy duty          | 80          |
| E903CP         | E900WF               | Push button           | RP72CP                  | Light duty                      | 30          |
| E908M          | E900WF               | Push button           | RP995BL                 | Heavy duty                      | 30          |
| E905           | E905WF               | Lever                 | RP995BL                 | Heavy duty                      | 80          |
| E906           | E905WF               | Lever                 | RP991BL                 | Heavy duty with fine adjustment | 80          |
| E907M          | E905WF               | Lever                 | RP907S                  | Flexible snake arm F/A          | 80          |
| E910           | E905WF               | Lever                 | RP999                   | Mechanical one piece            | 80          |
| E909           | 834                  | Non-switchable        | RP909FIT                | One pillar                      | 14          |