



15 SEALING RIBS MUST BE
FREE OF SINKS, VOIDS
KNIT LINES AND FLASH



14 SEALING RIBS MUST BE
FREE OF SINKS, VOIDS,
—KNIT LINES AND FLASH.



30 **make**
K C CONSTANT




5-7
3X C CO



36-37
-2X C CONST



make
12
K C CONSTANT



SECTION G-G

 [Return to top of page](#)

PART NO	REV	STATUS	MATERIAL SPECIFICATION	COLOR	TYPE	QTY	BA	QTY	BA	REPLACED BY	TYPICAL MATING CONNECTOR (REF)
---------	-----	--------	------------------------	-------	------	-----	----	-----	----	-------------	--------------------------------

NOTES

1. UNLESS OTHERWISE SPECIFIED AND/OR INDICATED:
DIMENSIONS ARE TO FACE OF VIEW SHOWN AND
AUTOMATICALLY ROUNDED BY COMPUTER FOR INSPECTION
(SEE MATH MODEL FOR PRECISE DIMENSIONS). FOR ALL
OTHER DIMENSIONS NOT SHOWN BUT REQUIRED FOR TOOL
BUILD, SEE MATH MODEL FOR PRECISE TOOL PATH DATA.
2. PARTS ARE TO BE PACKAGED IN SEALED PLASTIC BAGS. GROSS
WEIGHT INCLUDING CARTON IS NOT TO EXCEED 34 POUNDS.
3. "▲" DENOTES DIMENSIONS THAT ARE CONTROLLED FOR AUTOMATIC
PROCESSING.

ALL DIMENSIONS ARE IN MILLIMETERS	
REFERENCE	DRAWING NAME

4527051

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

[Delphi Connection Systems:](#)

[12052893-B](#)