


A
B
C
D
E
F






1> FIGURE OF INSERTION

HORIZONTALLY ○

DF57H-4S-1.2C

DIAGONAL ×

DF57-***SCF




NOTE 1> AVOID ANGLED INSERTION OF CRIMP CONTACT(DF57-***SCF) TO MAINTAIN PERFORMANCE RELIABILITY.

部番		材 質		処 理 , 備 考		1	PBT	UL94V-0, NATURAL(WHITE)
UNITS		SCALE		訂 正 記 事		設 計		検 図
mm		20 : 1		△の数		年 月 日		
HRS		HIROSE ELECTRIC CO., LTD.		承認 : KI. AKIYAMA 12.03.19		図番 : EDC3-343901-00		
				検 図 : HK. UMEHARA 12.03.19		製品名 : DF57H-4S-1.2C		
				設 計 : TS. KUMAZAWA 12.03.19		製品コード : CL666-0101-9-00		
				製 図 : TS. KUMAZAWA 12.03.19				△ 1/2


DF57 Series Mating / Unmating Operation Instruction

Mating


①By positioning the convexity of the socket sides to the header concavity, align the centers of the socket and the header in pitch direction.



②Slightly press the socket down at cable side to tilted angle.




③Press down at the lever side with stabilizing the cable side to insert. Mating completes.




Unmating


①Hook the lever with finger nail.



②Lift up to the upper direction and friction lock is released.



③Lift up to the upper direction and positive lock is released. Removal completes.



HRS

DRAWING NO.	EDC3-343901-00
PART NO.	DF57H-4S-1.2C
CODE NO.	CL666-0101-9-00

△ 2/2