

4

3

2

1

THIS DRAWING IS UNPUBLISHED.		RELEASED FOR PUBLICATION		LOC	DIST	REVISIONS							
C COPYRIGHT		ALL RIGHTS RESERVED.				P	LTR	DESCRIPTION			DATE		
						C1		ECR-14-001896			13FEB2014		
											GK HMR		

REPLACED BY OCEAN STYLE APPLICATOR PART

NUMBER 2151514-2

FOR REPLACEMENT PARTS FOR APPLICATOR 1530114
 REFER TO ADDITIONAL PAGE(S). SPARE PARTS KIT (IF LISTED)
 WILL REMAIN AVAILABLE.

THE REPLACEMENT OCEAN STYLE APPLICATOR HAS THE
 SAME TERMINATOR/PRESS INTERFACE AS APPLICATOR
 1530114

THIS DRAWING IS A CONTROLLED DOCUMENT.		DWN GOPALAKRISHNA HV		TE Connectivity	
DIMENSIONS:		CHK RAGHAVENDRA			
		APVD RAGHAVENDRA			
TOLERANCES UNLESS OTHERWISE SPECIFIED:		PRODUCT SPEC			
0 PLC ±		APPLICATION SPEC			
1 PLC ±					
2 PLC ±					
3 PLC ±					
4 PLC ±					
ANGLES ±		WEIGHT		RESTRICTED TO	
MATERIAL		CUSTOMER DRAWING		A3	
FINISH		DRAWING NO		C- 1530114	
		SCALE		SHEET 1 OF 2	
		REV C1			

THIS DRAWING IS UNPUBLISHED.		RELEASED FOR PUBLICATION		20
(C) COPYRIGHT 20		BY TICO ELECTRONICS CORPORATION ALL RIGHTS RESERVED.		
PART NUMBER	REV	TERMINATOR	FEED TYPE	DESCRIPTION
1530114-1	C	LEADMAKER	PNEUMATIC	CUTS CARRIER
1530114-2	C	BENCH	PNEUMATIC	CUTS CARRIER
1530114-6	C	LEADMAKER	PNEUMATIC	CONTINUOUS CARRIER
7-1530114-1	C	LEADMAKER	PNEUMATIC	-1 AND SPARE PARTS
7-1530114-2	C	BENCH	PNEUMATIC	-2 AND SPARE PARTS
7-1530114-6	C	LEADMAKER	PNEUMATIC	-6 AND SPARE PARTS
7-1530114-7	A	-	-	SPARE PARTS KIT


LOC	DIST	REVISIONS					
		P	LTR	DESCRIPTION	DATE	OWN	APVO
SET UP GAGE	A	66	A	RELEASED	08MAY2001	BH	BH
458637-3			B	ECR-10-005746	16MAR2010	YY	TE
			BI	ECR-10-007407	07APR2010	C.C	S.X
			C	ECR-10-008177	16APR2010	V.V	S.V

▲ RECOMMENDED SPARE PARTS

2. GREASE RAM, CAM, CAM FOLLOWER AND FEED ROD LIGHTLY.
3. CERTAIN TERMINALS REQUIRE LUBRICATION. REFER TO THE TERMINATING UNITS DOCUMENTATION.
4. LUBRICATE DAILY PER THE APPLICATOR INSTRUCTION SHEET SUPPLIED WITH THE APPLICATOR.

5 CUT TO LENGTH AT ASSEMBLY

* WARNING
ON INSTALLATION, SET WIRE
DISC TO LARGEST WIRE SIZE
SETTING. USE OF SETTINGS
BELOW MIN. REQUIRED CRIMP
HEIGHT SETTING WILL CAUSE
DAMAGE TO CRIMP TOOLING.



Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

[TE Connectivity:](#)

[1530114-2](#)