



Technical drawing of a bolted joint. The drawing shows a cross-section of a bolt and nut assembly. Dimension A indicates the thickness of the flange. Dimension H indicates the length of the bolt. Dimension C indicates the length of the nut.

NOTES:

1. MATERIAL: HIGH COPPER CONTENT
HARD DRAWN ROD
2. USED FOR CONNECTING CONDUCTORS
TO VARIOUS SIZES OF TAPPED HOLE

[illegible]

PANDUIT

CORP. TINLEY PARK, ILLINOIS

BRONZE SERVICE POST CONNECTORS, TYPE SP1
CUSTOMER DRAWING

DESCRIPTION

ECN

SCALE
N/A

DRAWING NO / CAD FILE

C41213_02