

Part Number: 07010



CALIBRATION UNIT, NIST STD WS & FG

- Passive device
- No power source required
- NIST traceable
 - Allows in-house NIST traceable calibration
- Wrist strap test range:
 - 750 Kilohm - 100 Megohm
- Foot ground test range:
 - 750 Kilohm - 100 Megohm
- Monitoring and control instruments are out of the scope of RoHS
- Made in America
- NOTE: The 07010 can be used with the Desco [19250](#), [19252](#), [19253](#), [19350](#) and [19351](#).
- Wrist strap test range: 750K-10M
 - Foot ground test range: 750K-100M