



Product Discontinuance:

RN IDH Series Headers, Non-Press Fit

Date: September 28, 2001
Issue Number: 447

To: 3M Interconnect Solutions Division Global Copy List
3M Interconnect Solutions Division Authorized Distributors
3M Interconnect Solutions Division Customers

Product:
IDH Series Headers, Non-Press Fit

IDH-xxPKxx-S3-xx
IDH-xxPKxx-SR3-xx

IDH-xxLP-S3-xx
IDH-xxLP-S4-xx
IDH-xxLP-SR3-xx

Effective September 28, 2001 3M will be discontinuing the Robinson Nugent IDH product family known, with the exception of the **IDH press fit headers with “PS” tail option**. The non-press fit product numbers have been omitted from the September 1, 2001 price page update, distributed August 24, 2001.

The IDH press fit product family coded with tail option “PS” will not be affected by the product discontinuance (IDH-xxPKx-PS-xx). These products will remain available, and will be included in a price page reprint.

This IDH non-press fit product offering is replaced by the 3M 3000 Series and 2500 Series header products. A family cross-reference for these products is included for switching customer specifications where applicable.

Actions Required

- Please notify affected customers of this discontinuation and utilize the attached cross-reference to qualify 3M replacements.
- All orders must be received by October 31, 2001 and scheduled for immediate delivery.
- Distribution may return discontinued items in original standard packages at currently published distributor prices. Robinson Nugent’s standard packaging and current distributor prices are listed in Robinson Nugent’s price page dated September 30, 1997. Please reference the included file labeled “Robinson Nugent 9-30-97 Price Page.” Products identified by Robinson Nugent as returnable in this attachment, will be accepted for return.

Returning Discontinued Product

Requests for return must be submitted, in writing, to the distributor's customer service representative by **October 30, 2001**. The request will be reviewed and the distributor will be notified of a RMA number and the 3M location the product should be returned. Product must be received at the designated 3M location by **November 30, 2001** to be honored for credit.

Please direct any correspondence on this matter to:
Chris Savinsky, Product Marketing
Copper Interconnect Solutions
Phone: 512-984-6514
e-mail: cbsavinsky@mmm.com

RN IDH L/E to 3M Cross Reference	
RN Product Family	3M 3000 Series (TS-0772)
IDH-XXPK-S3-TR (or TG)	Pin Count ID -6002UG
IDH-XXPK2-S3-TR (or TG)	Pin Count ID -6602UG
IDH-XXPK1-S3-TR (or TG)	
IDH-XXPK-S3-TG30	Pin Count ID -6002UB
IDH-XXPK2-S3-TG30	Pin Count ID -6602UB
IDH-XXPK1-S3-TG30	
IDH-XXPK-SR3-TR (or TG)	Pin Count ID -5002UG
IDH-XXPK2-SR3-TR (or TG)	Pin Count ID -5602UG
IDH-XXPK1-SR3-TR (or TG)	
IDH-XXPK-SR3-TG30	Pin Count ID -5002UB
IDH-XXPK2-SR3-TG30	Pin Count ID -5602UB
IDH-XXPK1-SR3-TG30	

RN IDH LP to 3M Cross Reference	
RN Product Family	3M 2500 Series (TS-0770)
IDH-XXLP-S3-TR (or TG)	25XX-6002UG
IDH-XXLP-S3-TG30	25XX-6002UB
IDH-XXLP-S4-TR (or TG)	25XX-6003UG
IDH-XXLP-S4-TG30	25XX-6003UB
IDH-XXLP-SR3-TR (or TG)	25XX-5002UG
IDH-XXLP-SR3-TG30	25XX-5002UB

Important Notice

All statements, technical information, and recommendations related to 3M's products are based on information believed to be reliable, but the accuracy or completeness is not guaranteed. Before using this product, you must evaluate it and determine if it is suitable for your intended application. You assume all risks and liability associated with such use. Any statements related to the product which are not contained in 3M's current publications, or any contrary statements contained on your purchase order shall have no force or effect unless expressly agreed upon, in writing, by an authorized officer of 3M.

Warranty; Limited Remedy; Limited Liability.

This product will be free from defects in material and manufacture for a period of one (1) year from the date of purchase. **3M MAKES NO OTHER WARRANTIES INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.** If this product is defective within the warranty period stated above, your exclusive remedy shall be, at 3M's option, to replace or repair the 3M product or refund the purchase price of the 3M product. **Except where prohibited by law, 3M will not be liable for any loss or damage arising from this 3M product, whether direct, indirect, special, incidental or consequential regardless of the legal theory asserted.**



Interconnect Solutions Division

6801 River Place Blvd.

Austin, TX 78726-9000

www.3M.com/interconnects

© 3M IPC 80-4000-0316-8