

### AC1127 → Carrying case for HP21 & HP22



for following equipment (not included):

- Handheld instrument HP21 / HP22
- Max. 2 HC2-S probes
- calibration device ER-15
- 1 package of humidity standard EA50-SCS