

9100S/9102S Handheld
Dry-Well



Highlights (/products/process-calibration-tools/temperature-calibrators/field-temperature-sources/9100s9102s-hand?quicktabs_product_details=0)

Description (/products/process-calibration-tools/temperature-calibrators/field-temperature-sources/9100s9102s-hand?quicktabs_product_details=1)

Specifications (/products/process-calibration-tools/temperature-calibrators/field-temperature-sources/9100s9102s-hand?quicktabs_product_details=2)

Models and Accessories (/products/process-calibration-tools/temperature-calibrators/field-temperature-sources/9100s9102s-hand?quicktabs_product_details=3)

Knowledge and Information (/products/process-calibration-tools/temperature-calibrators/field-temperature-sources/9100s9102s-hand?quicktabs_product_details=4)

Model Name	Description	
9100S-A	HDRC Handheld Dry-Well A	
	Accessory	Description
	9300	Rugged Carrying Case: 9100S
9100S-B	HDRC Handheld Dry-Well B	
	Accessory	Description
	9300	Rugged Carrying Case: 9100S
9100S-C	HDRC Handheld Dry-Well C	
	Accessory	Description
	9300	Rugged Carrying Case: 9100S
9100S-D	HDRC Handheld Dry-Well D	
	Accessory	Description
	9300	Rugged Carrying Case: 9100S
9102S	HDRC Handheld Dry-Well	
	Accessory	Description
	3102-0	Insert, blank : 9102S
	3102-1	Insert, 1/16 in (1.6 mm) : 9102S
	3102-2	Insert, 1/8 in (3.2 mm) : 9102S
	3102-3	Insert, 3/16 in (4.8 mm) : 9102S
	3102-4	Insert, 1/4 in (6.4 mm) : 9102S
	3102-5	Insert, 5/16 in (7.9 mm) : 9102S
	3102-6	Insert, 3/8 in (9.5 mm) : 9102S
	3102-7	Insert, 7/16 in (11.1 mm) : 9102S
	3102-8	Insert, 5/32 in (4 mm) : 9102S
	9308	Rugged Carrying Case : 9102, 9132, 9140

Accessories common to all models:

Accessory	Description
SC1-HHDW	Silver CarePlan, 1 Yr, Handheld Dry-Well
SC2-HHDW	Silver CarePlan, 2 Yr, Handheld Dry-Well
SC4-HHDW	Silver CarePlan, 4 Yr, Handheld Dry-Well