


High-precision Visual Displacement Measurement System

Z300

2-Dimensional CCD is Built in. A New Type of Displacement Sensor Utilizing the Best and Most Up-to-date Image Processing Technologies.



Features

Stable measurement of a transparent object or a glass.
 A wide variety of sensor heads for enhanced detection possibilities.

OMRON's Z300 makes the notion that displacement sensors cannot perform stable measurement of a transparent object or a glass a thing of the past. The newly-developed 2-dimensional CCD (S-CCD) incorporated in the Z300, combined with upgraded performance of the controller, provides enhanced stability and accuracy in measurement of a transparent object. The latest algorithm employed by the Z300 enables optimal sensitivity even if there is a big difference between the amount of reflected light from the surface and that from the bottom of a glass.

Enhanced measurement area and a variety of high-resolution, long-distance sensor heads greatly expand the range of applications.

The Z300 is just another example of OMRON's ongoing challenge to the limits of sensing possibilities.

Z300-S60
 Super Long-range Model
 Detection distance of 600 ± 350 mm

Z300-S10
 Long-range Model
 Detection distance of 100 ± 20 mm


Z300-S5T
 High-precision Model
 Detection distance of 50 ± 5 mm

Z300-S2T
 Super-precision Model
 Detection distance of 20 ± 1 mm

The innovative 2-dimensional CCD (S-CCD) is the key to the sensing performance.

The 2-dimensional CCD enables stable, high-speed measurement.

A conventional displacement sensor using a 1-dimensional CCD cannot deal with flutter influence to the output. Therefore, the sensor requires increased number of measurements for signal averaging, which leads to slow response time. The S-CCD with a 2-dimensional CCD has solved this disadvantage, by splitting the measurement point into 60 lines for measurement in finer detail. The value per each pixel is then averaged to produce a reliable output, free from flutter influence caused by the object's surface condition. Stable detection and high-speed processing is thus possible with the Z300.





CCD makes a difference in measurement of a transparent object.

PSD sensor

A PSD sensor using diffuse reflection is virtually prevented from performing measurement due to insufficient reflection distribution from the surface. A sensor using the mirror reflection method, on the other hand, receives reflective light from the bottom or background of the object, which causes an error in determining the target position, impeding accurate measurement.

CCD sensor

A CCD using the mirror reflection method is a solution. It can extract only the light reflected off the surface of the target. Accurate measurement of a transparent object is possible without being affected by reflected light from the bottom or background of the object.




Monitoring as the object is being measured.
Measurement data can be recorded and played back.

Easy-to-see color display is another great feature of the Z300 (when connected to a color monitor). Monitoring at each key stage including test and adjustment, operation, or maintenance greatly facilitates efficient, error-free measurement.


Real-time monitoring

Digital monitor




The measured value is displayed. The use of two colors: green for "Pass" judgement, and red for "High/Low," enhances visual recognition of the measurement result.

Image monitor



Displays the position of measurement point as well as intensity of the reflected light. Conveniently checks whether optimum measurement is taking place.


Trend monitor



Continuous measurement values during a certain period of time are shown in chronological order. Changes in the measured values of a moving or rotating object can be checked at a glance.


Monitoring during recording and playback

Test mode




Any desired number of measurement data can be stored for testing with a workpiece.

Conditions during Test mode can be recorded and played back



Test measurement data obtained off-line can be saved for reference for actual in-line measurement.

NG (High/Low) judgement status is recorded and played back.




Up to 20 in-line NG data (information including reflected light condition and measurement data) can be recorded for workpiece analysis as well as for troubleshooting.

Interactive menus provide a variety of measurement functions.

Application menu

Settings for measurement methods are easily performed using the menu.

Just follow the guidance of the monitor screen.



Expert menu


Expert menu is available for more advanced measurement. Detailed setting conditions can be conveniently programmed using the menu.

Enhanced hold functions widen the scope of application.


With discrete hold functions equipped within the controller, the Z300 provides a variety of trigger (measurement timing) functions, making otherwise difficult applications a reality — with ease.

Hold functions


Sampling hold




Peak hold (bottom)




Peak to peak hold




Average hold



Length hold




Selectable trigger function




Measurement trigger can be set to the controller for desired measurement timing.

Application


Measuring the thickness of transparent film




Measurement of electrode position in the display module




Measuring the thickness of sheet




Measurement of warping in transparent plastic




Inspecting the surface uniformity of a hard disk




Shape measurement for welding robot control




Measuring tire or black rubber thickness



Grinding measurement of a whetstone



System configuration









Ordering Information

Name	Item	Model	Remarks
Sensor		Z300-S2T	
		Z300-S5T	
		Z300-S10	
		Z300-S60	
Controller		Z300-VC10EV3	NPN input/output
		Z300-VC15EV3	PNP input/output
Console		Z300-KP	
Liquid Crystal Monitor		F150-M05L	
Sensor Extension Cable		Z309-SC1R (See note)	Cable length: 1.5 m, 3 m, 6 m, 8 m, 13 m or 18 m
Monitor Cable		F150-VM	

Note: Specify the required cable length when ordering.

Rating/performance


Sensor: Z300-S2T/Z300-S5T/Z300-S10/Z300-S60

Model		Z300-S2T		Z300-S5T		Z300-S10		Z300-S60			
		Diffuse reflection	Mirror reflection	Diffuse reflection	Mirror reflection	Diffuse reflection	Mirror reflection	Diffuse reflection only			
											
Measurement mode											
Distance to measurement center		±5.2 mm	20 mm (with beam cover attached: 16 mm)	±50 mm	±44 mm	±100 mm	±94 mm	±600 mm			
Measurement range		±1 mm		±5 mm	±4 mm	±20 mm	±16 mm	±350 mm (F.S.700 mm)			
Light source		Visible-light semiconductor laser (Wavelength: 650 nm, 1 mW max., Class 2)		Visible-light semiconductor laser (Wavelength: 670 nm, 1 mW max., Class 2)				Visible-light semiconductor laser (Wavelength: 658 nm, 15 mW max., Class 3B)			
Beam dimensions (See note 1.)		20 μm × 300 μm (200 μm*) TYP. (distance to measurement center) * Measurement region		30 μm × 400 μm TYP. (distance to measurement center)		60 μm × 1000 μm TYP. (distance to measurement center)		0.3 mm × 16 (10.3*) mm (at 500 mm) * Measurement region			
Linearity		±0.05 %F.S. (See note 2.)	±0.05 %F.S. (See note 3.)	±0.1 %F.S. (See note 4.)				±0.07 %F.S. (250 to 750 mm) ±0.1 %F.S. (750 to 950 mm) (See note 4.)			
Resolution		0.4 μm (See notes 5 and 6.)		0.4 μm (See notes 7 and 9.)		1 μm (See notes 7 and 8.)		8 μm (at 350 mm) 40 μm (at 600 mm) (See notes 7 and 8.)			
Sampling period (See note 10.)		540 μs									
LED indicators	NEAR indicator	Lights if the workpiece is close to the measurement center or is on the near side of the measurement center and inside the measurement region. Flashes if the workpiece is outside the measurement region or if the density is excessive or insufficient.									
	FAR indicator	Lights if the workpiece is close to the measurement center or is on the far side of the measurement center and inside the measurement region. Flashes if the workpiece is outside the measurement region or if the density is excessive or insufficient.									
Temperature characteristic (See note 11.)		±0.01 %F.S./°C									
Environment resistance	Degree of protection	IEC IP64		IEC IP67				IEC IP66			
	Ambient operating illumination	Illumination at light-receiving surface: 3,000 lx max., incandescent light									
	Ambient temperature	Operating: 0 to +50 °C, Storage: -15 to +60 °C (with no icing or condensation)									
	Ambient humidity	Operating and storage: 35 % to 85 % (with no condensation)									
	Vibration resistance	10 to 150 Hz (double amplitude: 0.35 mm) for 8 min. each in X, Y, and Z directions									
Materials		Unit: Die-cast aluminum; Cable sheathing: Heat-resistant chlorinated vinyl Connector: Zinc alloy and brass									
Cable length		2 m							50 cm		
Minimum bending radius		68 mm									
Weight		Approx. 600 g (Unit: Approx. 350 g)		Approx. 800 g (Unit: Approx. 600 g)				Approx. 800 g (Unit: Approx. 700 g)			
Accessories		3 ferrite cores, laser warning labels (English)									

Note: 1. Defined at 1/e² (13.5 %) of the density at the light center. Light may, however, be present outside this range and if the reflection factor of the light around the workpiece is high compared to the workpiece, measurement may be affected.

2. Error with respect to the theoretical line representing the displacement output for measurement of OMRON standard SUS blocks. The linearity varies with the type of workpiece.

3. Error with respect to the theoretical line representing the displacement output for measurement of OMRON standard quartz glass. The linearity varies with the type of workpiece.
4. Error with respect to the theoretical line representing the displacement output for measurement of OMRON standard white alumina ceramics. The linearity varies with the type of workpiece.



5. Displacement conversion value for peak-to-peak of displacement output. These figures are for measurement of OMRON standard quartz glass (mirror reflection mode) or OMRON standard SUS blocks (diffuse reflection) at the measurement center.
In magnetic fields, it may not be possible to maintain resolution performance characteristics.
6. These figures are for when the Sensor is connected to the Z300-VC10EV3/VC15EV3, the average number of measurements is 256, and M command RS-232C output is used.
7. Displacement conversion value for peak-to-peak of displacement output (for measurement of OMRON standard white alumina ceramic at the measurement center).
In strong magnetic fields, it may not be possible to maintain resolution performance characteristics.
8. With the Z300-VC10EV3/VC15EV3, at an average number of measurements of 64.
9. With the Z300-VC10EV3/VC15EV3, at an average number of measurements of 512.
10. Value for measurement with 1 line (high speed) set in CCD Mode.
11. Value for measurement with the space between the Sensor and the workpiece (Z300-S5T/S10/S60: white alumina ceramic; Z300-S2T: quartz glass) secured with an aluminum jig.

Controller: Z300-VC10EV3/Z300-VC15EV3

Item mode		VISUAL mode	NON-VISUAL mode
Performance specifications	Number of Sensors that can be mounted	2	1
	Number of scenes	16	1
	Image memory function	NG images: 20 scenes max.; Surrounding images: 4 scenes max.; Workpiece display images: 4 scenes max.	—
	Processing method	Gray center of gravity, edge centering	Edge centering
	Pre-image processing	Noise removal, smoothing	None
	Averaging/filtering	Average number of times (12 stages, 1 to 4096 times), HPF (high pass filter)	Average number of times (SLOW: 64 times; FAST: 1 time)
	Light intensity tracking function	Automatic (The light intensity tracking range can be specified.) Fixed (Select from 32 stages.)	Automatic (The light intensity tracking range can not be specified.) Fixed (Select either HIGH or LOW.)
	Applications	Select from the following 8 types: Surface displacement, spot displacement, maximum height, groove/indentation, level difference, transparent workpiece thickness, level difference (2 Sensors), or thickness (2 Sensors).	—
	Region specification	Region specification of line beam and displacement direction is possible.	—
	Two region measurement modes	Absolute coordinate mode and relative coordinate mode	—
	Hold functions	Sampling, peak, bottom, peak-to-peak, average, and length	—
	Two Sensor measurement modes	Simultaneous measurement and alternate measurement	—
	Measurement data	4 outputs per scene	1 output
	Equations	The following operations are possible for outputs 0 to 3: K+A, K-A, K+(A+B), K-(A-B), and K-(A+B) A and B: Specified measurement points K: Freed constant	—
	Results output	Judgement output (HIGH, PASS, LOW, ERROR) RS-232C output Terminal block output Measurement value output (measurement value) RS-232C output Terminal block output Analog output	Analog output
	Terminal block	11 input points: <u>TRIGGER</u> , <u>HOLD-RESET</u> , <u>LD-OFF</u> , <u>ALL-ZERO</u> , <u>ZERO0</u> , <u>ZERO1</u> , <u>RESET</u> , and DI 0 to DI 3 21 output points: <u>DO0</u> to <u>DO20</u>	<u>LD-OFF</u>
	Input/Output Type	Z300-VC10EV3: NPN Z300-VC15EV3: PNP	
	Monitor interface	1 channel (for pin jack or overscan monitor)	—
	Analog output resolution	The full scale for output can be divided into a maximum of 40000 gradations. Resolution (See note.) * 0.25 mV (±5 V), 0.4 μA (4 to 20 mA)	

Note: For measurement at an average number of times of 64 with an OMRON K3AS Linear Sensor Controller connected.

Item	mode	VISUAL mode	NON-VISUAL mode
General specifications	Supply voltage	21.6 to 26.4 VDC (including ripple)	
	Current consumption	1 A max. (with 2 Sensors connected)	
	Insulation resistance	20 MΩ min. between all DC external terminals and GR terminal (100 VDC Megger, with internal surge absorber removed)	
	Dielectric strength	1000 VAC, 50/60 Hz between all DC external terminals and GR terminal (with internal surge absorber removed)	
	Leakage current	10 mA max.	
	Noise resistance	1500 Vp-p; Pulse width: 0.1 μs/ 1 μs; Rising edge: 1-ns pulse	
	Vibration resistance	10 to 150 Hz (double amplitude: 0.1 mm) for 8 min. each in X, Y, and Z directions	
	Shock resistance	200 m/s ² , 3 times each in 6 directions	
	Ambient temperature	Operating: 0 to +50 °C, Storage: -15 to +60 °C (with no icing or condensation)	
	Ambient humidity	Operating and storage: 35 % to 85 % (with no condensation)	
	Ambient environment	No corrosive gases	
	Ground	Ground the Z300's ground terminal to less than 100 Ω	
	Degree of protection	IEC60529 IP20 (in-panel)	
	Case material	Controller: ABS	
	Weight (including packaging)	Approx. 1300 g (Unit: Approx. 700 g)	
	Accessories	2 manuals, 1 resistor (250 Ω, 1/2 W)	

Monitor

Item	Monitor Model	Liquid Crystal Monitor F150-M05L
Size		5.5 inches
Type		TFT color liquid crystal
Resolution		320 × 240 dots
Input signal		NTSC composite video (1.0 V / 75 Ω)
Supply voltage		20.4 to 26.4 VDC
Current consumption		Approx. 700 mA
Ambient temperature		Operating: 0 °C to +50 °C, Storage: -25 °C to +65 °C (with no icing or condensation)
Ambient humidity		Operating and storage: 35 to 85 %RH (with no condensation)
Weight (including packaging)		Approx. 870 g (Unit: Approx. 610 g)
Accessories		Operation manual, 4 mounting brackets

Laser Safety

The Z300-S2T, Z300-Z5T and Z300-S10 Sensor Heads are Class 2 Laser Products according to EN60825-1 (IEC60825-1) and Class II Laser Product according to FDA (21 CFR1040.10) (see note). The Z300-S60 Sensor Head is a Class 3B and Class IIIB Laser Product, respectively. The Z300 Series is meant to be built into final system equipment. Pay special attention to the following precautions for the safe use of the product:

Note: Europe: Class 2 and Class 3B of EN60825-1: 1994 = IEC60825-1: 1993
U.S.A.: Class II and Class IIIB of FDA (21 CFR1040.10)

	Z300-S2T	Z300-S5T	Z300-S10	Z300-S60
Wavelength	650 nm	670 nm		658 nm
Peak power	1 mW max.			15 mW max.
Class	2			3B
Maximum pulse duration	7 ms			17.5 ms
Period	0.5 to 10 ms			0.5 to 25 ms

- (1) Use this product as specified in the operation manual. Otherwise, you may be exposed to hazardous laser radiation.
- (2) The Z300 series radiates laser beams in the visible light range. Do not expose your eyes directly to the laser radiation. Ensure that the laser beam path is terminated during use. If a mirror or shiny surface is positioned in the laser beam path, ensure that the reflected beam path is also terminated.
If the Unit must be used without terminating the laser beam path, position the laser beam path so that it is not at eye level.
- (3) To avoid exposure to hazardous laser radiation, do not displace nor remove the protective housing during operation, maintenance, and any other servicing.
- (4) The user should return the product to OMRON for all repair and servicing.
- (5) As for countries other than those of Europe and the U.S.A., observe the regulations and standards specified by each country.

Precautions


Warming up

After turning on the power, wait about 30 minutes before using the equipment. The circuits are not stable after turning on the power, and thus measured values tend to gradually drift.


Dimensions (Unit: mm)

Sensor


Z300-S2T




Z300-S5T



Z300-S10




Z300-S60




Controller

Z300-VC10EV3
Z300-VC15EV3




Console

Z300-KP



LCD monitor

F150-M05L



ALL DIMENSIONS SHOWN ARE IN MILLIMETERS.

To convert millimeters into inches, multiply by 0.03937. To convert grams into ounces, multiply by 0.03527.