Systems

Std.

0. Index

OptiCam® Pre-Polished Cam Fiber Optic Termination Kits

- For termination of all Panduit[®] OptiCam[®] Pre-Polished Connectors
- OptiCam® Termination Tool simplifies tooling and termination, and virtually eliminates operator error by providing visual indication of proper termination after the cam step has been completed
- No adhesive or electricity required for termination
- · Include installation instructions and stripping templates for all Panduit® OptiCam® Pre-Polished Connectors; also available on www.panduit.com



FCAMKIT



FPPKIT-CVY

Part Number	Part Description	Pkg. Qty.
OptiCam® Pre-Po	lished Cam Termination Kit	
FCAMKIT	Tools, consumables, installation instructions and stripping templates necessary for termination of all Panduit® OptiCam® Pre-Polished Cam Connectors.	1
OptiCam® Conve	rsion Kit – Converts Opti-Crimp® Termination Kit for	'

Optioaiii iciiiii	Spiroum remination			
FPPKIT-CVY	Converts Opti-Crimp® Termination Kits with the additional tools,	1		
	installation instructions, and stripping templates required for termination			
	of all Panduit® OptiCam® Pre-Polished Cam Connectors; includes			

OptiCam® Termination Tool and cradles, and FVFLPC-2.5SMY and FVFLPC-1.25SMY patch cords.

Cleaning Consumables Kit

	Replenishes the cleaning consumables required for termination of all fiber optic connectors; includes all of the same cleaning consumable items that are included in all Panduit termination kits.	1			

Field Polish Kit Upgrade for OptiCam® Connector Termination

FIELDKITUPG	Upgrades FIELDKIT with the additional tools, consumables, installation	1
	instructions and stripping templates required for termination of all	
	Panduit® OptiCam® Pre-Polished Cam Connectors.	

For field polish termination kits, refer to SA-NCCB51

Components for OptiCam® Pre-Polished Cam Termination Kits



OCTT



Part Number	Part Description	Std. Pkg. Qty.	Std. Ctn. Qty.	
Tools (included in FCAMKIT)				
FKITCASE	Case for fiber termination kits.	1	_	
CST115	Fiber cable jacket stripper.	1	_	
FALC	Alcohol bottle (empty).	1	10	
FBFSP	Fiber buffer stripper.	1	10	
FSCDVR	Screwdriver.	1	50	
FGLS	Safety glasses.	1	10	
FTWZR	Tweezers.	1	10	
FWBTL	Water bottle (empty).	1	10	
FKS	Fiber Kevlar shears.	1	10	
FWRKMAT	Fiber safe workmat.	1	10	
Tools (included in FCAMKIT and FIELDKITUPG)				
FIGOVE	Planet and a second and	-	40	

Tools (included i	in FCAMKIT and FIELDKITUPG)		
FJQCVR	Fiber cleaver tool.	1	10
ОСТТ	OptiCam® Termination Tool; includes batteries, pouch, and two cradles for each OptiCam® Connector – LC, SC, and ST (patch cords available separately).	1	_
FVFLPC-2.5SMY	Patch cord for all OptiCam® 2.5mm ferrule connectors (SC & ST).	1	10
FVFLPC-1.25SMY	Patch cord for all OptiCam® 1.25mm ferrule connectors (LC).	1	10
Cleaning Consumables (included in FCAMKIT and FCLEANKIT)			

FWP-C	Lint-free wipes.	100	1000
FSWB-C	Cleaning swabs.	100	1000
FSTY	Safety stickers for fiber scraps.	1	10
PFX-0	Permanent marking pen, fine tip, black ink (one included in each kit).	12	144

Replacement Parts

FJQCVRB	Replacement blade for FJQCVR.	1	10
FSCC	Tool cradles for SC OptiCam® Connectors (two per package).	1	_
FLCC	Tool cradles for LC OptiCam® Connectors (two per package).	1	_
FSTC	Tool cradles for ST OptiCam® Connectors (two per package).	1	

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

Panduit: FCAMKIT