



IS23SC1604

Features

- 16K bits (2K x 8) serial EEPROM with security logic
- Independent Security Codes for Data access after validation operations
- Provides transportation code security
- Manufactured with low power CMOS technology
- Single 5V supply with Vpp internally generated
- 2μs Read access time; 5mS Write/Erase time
- Operating temperature range from 0C to 70C
- Highly reliable 1,000,000 erase/write cycles; 10 years data retention


Security

- Data access only after validation of Security Codes
- Independent Read/Write protection of memory zones
- Permanent invalidation of Security Codes after eight false attempts
- Two security levels for Card Issuer and End User
- Permanent fuse protection on passwords and personal data

Description

IS23SC1604 is a low-cost and low power, highly secured 16K bits (2Kx8) serial EEPROM. It is fabricated using ISSI's advanced CMOS technology.

The IS23SC1604 provides 15704 bits of memory in four application zones. Each application zone is protected by multiple security codes independently from unauthorized read/write/erase access. An internal security fuse protects the personalized data written by card issuer.



Integrated Silicon Solution, Inc.



To Order

ISSI REGIONAL SALES OFFICES

Headquarters & West Coast Office

Santa Clara, California
PHONE: 408-588-0800
FAX: 408-588-0805
E-MAIL: sales@issi.com
www.issi.com

East Coast Office

Nashua, NH
PHONE: 603-594-4176
FAX: 603-594-4181
E-MAIL: gpolanec@msn.com

Central Office

Dallas, TX
PHONE: 972-488-9691
FAX: 877-716-5582
E-MAIL: lzastrow@flash.net

Europe Office

Devon, England
PHONE: 44-1752-764285
FAX: 44-1752-764289
E-MAIL: glouch@issi.com05

China Offices

Shanghai

PHONE: +86 21 5080 2288
FAX: +86 21 5080 2028
E-MAIL: issish@sh163c.sta.net.cn

Shenzhen

PHONE: 86755-663-3977
FAX: 86755-663-3984
E-MAIL: issi@public.szptt.net.cn

Suzhou

PHONE: 86512-725-0384
FAX: 86512-725-0536
E-MAIL: issisz@public1.sz.js.cn

Beijing

PHONE: 86-10-6824-3301
FAX: 86-10-6816-9097
E-MAIL: issibj@public.bta.net.cn


Hong Kong

PHONE: 852-2319-2211
FAX: 852-2319-2004



Integrated Silicon Solution, Inc.

SIO contact number	PAD name	Description
C1	Vcc	5V power Supply
C2	RST	Reset
C3	CLK	Serial Clock and Address Control
C4	FUS	Security fuse Pin
C5	GND	Ground
C6	N/C	No connec
C7	I/O	Bi-direction data input/output
C8	PGM	Programming control for(write/erase)



IS23SC1604



Integrated Silicon Solution, Inc.

