



Technical drawing of a bolted joint. The drawing shows a cross-section of a bolt and nut assembly. Dimension A indicates the thickness of the flange. Dimension H indicates the length of the bolt. Dimension C indicates the length of the nut. The bolt is shown with a hexagonal head and a threaded shank. The nut is shown with a hexagonal shape and a threaded shank. The drawing is a technical illustration of a bolted joint.

NOTES:

1. MATERIAL: HIGH COPPER CONTENT
HARD DRAWN ROD
2. USED FOR CONNECTING CONDUCTORS
TO VARIOUS SIZES OF TAPPED HOLE

[illegible]

PANDUIT CORP. TINLEY PARK, ILLINOIS

ANDRE CORP. TINLEY PARK, ILLINOIS

BRONZE SERVICE POST CONNECTORS, TYPE SP1
CUSTOMER DRAWING

SCALE	N/A	DRAWING NO / CAD FILE	C41213_02
-------	-----	-----------------------	-----------