

Part Number: 501588-0802

TFR Card Detect Switch Assy8CktEmbsTpPkg

Image not available

Status: OBSOLETE Replacement: 5015880804

Series: 501588
Category: Molex Parts

Series image - Reference only

## Product Environmental Compliance

EU RoHS: ELV and RoHS Compliant

China RoHS: © REACH SVHC:

Low-Halogen Status: Not Reviewed

## **Part Detail**

## General

Status

Category Series

Material Info

UPC 822350300216

## **Application Tooling**

Tooling specifications and manuals are found by selecting the products below.

Crimp Height Specifications are then contained in the Application Tooling Specification document.

Previously Available Application

Check our list of old tooling that used to be available for this part