



Thread-Repair-Kits



M

					Mftrs. List No.
M 2 x 0.4	2.1 mm	No. 2	No. 2	20	4001
M 2.5 x 0.45	2.6 mm	No. 3	No. 3	20	4003
M 3 x 0.5	3.2 mm	No. 4	No. 4	20	4005
M 3.5 x 0.6	3.7 mm	No. 5	No. 5	20	4006
M 4 x 0.7	4.2 mm	No. 6	No. 6	20	4007
M 5 x 0.8	5.2 mm	No. 8	No. 8	20	4009
M 6 x 1.0	6.3 mm	No. 9	No. 9	20	4010
M 7 x 1.0	7.3 mm	No. 10	No. 11	20	4011
M 8 x 1.25	8.3 mm	No. 11	No. 11	20	4012
M 8 x 1.0	8.3 mm	No. 11	No. 11	20	4013
M 9 x 1.25	9.3 mm	No. 12	No. 12	15	4014
M 10 x 1.5	10.4 mm	No. 13	No. 13	15	4016
M 10 x 1.25	10.3 mm	No. 13	No. 13	15	4017
M 10 x 1.0	10.3 mm	No. 13	No. 13	15	4018
M 11 x 1.5	11.4 mm	No. 14	No. 14	10	4019
M 12 x 1.75	12.4 mm	No. 15	No. 15	10	4021
M 12 x 1.5	12.4 mm	No. 15	No. 15	10	4022
M 12 x 1.25	12.3 mm	No. 15	No. 15	10	4023
M 12 x 1.0	12.3 mm	No. 15	No. 15	10	4024
M 14 x 2.0		No. 16		10	4028
M 14 x 1.5		No. 16		10	4029
M 14 x 1.25		No. 17		10	4030
M 14 x 1.0		No. 17		10	4031
M 16 x 2.0		No. 18		10	4032
M 16 x 1.5		No. 18		10	4033
M 18 x 2.5		No. 20		5	4034

M 18 x 2.0		No. 20		5	4035
M 18 x 1.5		No. 20		5	4036
M 20 x 2.5		No. 21		5	4037
M 20 x 2.0		No. 21		5	4038
M 20 x 1.5		No. 21		5	4039
M 22 x 2.5		No. 22		5	4040
M 22 x 2.0		No. 22		5	4041
M 22 x 1.5		No. 22		5	4042
M 24 x 3.0		No. 23		5	4043
M 24 x 2.0		No. 23		5	4044
M 24 x 1.5		No. 23		5	4045