

NO WARRANTY, EXPRESSED OR IMPLIED, IS MADE BY PANDUIT WITH RESPECT TO ADHESIVE BOND PERFORMANCE. AMONG OTHER THINGS, THE CONDITIONS UNDER WHICH THESE MOUNTS MAY BE APPLIED AND/OR THE SURFACE TO WHICH THEY MAY BE APPLIED ARE BEYOND PANDUIT'S CONTROL.

|     |          |      |     |                                                                       |          |   |   |      |     |  |
|-----|----------|------|-----|-----------------------------------------------------------------------|----------|---|---|------|-----|--|
|     |          |      |     |                                                                       |          |   |   |      |     |  |
|     |          |      |     |                                                                       |          |   |   |      |     |  |
|     |          |      |     |                                                                       |          |   |   |      |     |  |
|     |          |      |     |                                                                       |          |   |   |      |     |  |
| 3   | 12-1-00  | CGSM |     | ADDED NEW PART# ABM50 FOR JAPAN PARTS                                 | GB0239DQ | 3 |   |      |     |  |
| 2   | 10-30-00 | CGSM |     | REMOVED DIM, CHANGED DIMENSIONS TO REF,<br>EDITED NOTES, ADDED NOTE 3 | GB0239DQ | 2 |   |      |     |  |
| 1   | 9-15-00  | CGSM |     | CHANGED HOLE SIZE DIMENSION                                           | GB0239DQ | 1 |   |      |     |  |
| R   | 8-29-96  | CJG  |     | INITIAL RELEASE                                                       | GB0239DQ | R |   |      |     |  |
| REV | DATE     | BY   | CHK | DESCRIPTION                                                           | ECN      | - | R | CUST | SUP |  |