

Double Row Terminal Blocks

670A RZ Series

300 Volts



Specifications:

- Base, Thermoplastic, 130°C (U.L. RTI)
- Closed Back Design
- Screws, #6-32 Binder Head, Phil-Slot, Steel
- Terminals, Plated Brass
- 1-30 Poles
- 3/8" Centers
- The Suitability Of These Devices For Greater Currents Shall Be Determined In The End-Use Application
- Wire Range With Wire Binding Screw #12-#22 AWG – 20 Amps
- Wire Range With Sems Pressure Screw #14-#22 AWG Stranded Or Solid Wire (Cat. Designation 3865)
- UL Recognized File No. XCFR2.E47811
- CSA Certified File No. LR19766
- CE

Catalog #	# of poles	Dimensions	
		A	B
670A RZ 01	1	1.03	0.75
670A RZ 02	2	1.41	1.13
670A RZ 03	3	1.78	1.50
670A RZ 04	4	2.16	1.88
670A RZ 05	5	2.53	2.25
670A RZ 06	6	2.91	2.63
670A RZ 07	7	3.28	3.00
670A RZ 08	8	3.66	3.38
670A RZ 09	9	4.03	3.75
670A RZ 10	10	4.41	4.13
670A RZ 11	11	4.78	4.50
670A RZ 12	12	5.16	4.88
670A RZ 13	13	5.53	5.25
670A RZ 14	14	5.91	5.63
670A RZ 15	15	6.28	6.00

Catalog #	# of poles	Dimensions	
		A	B
670A RZ 16	16	6.66	6.38
670A RZ 17	17	7.03	6.75
670A RZ 18	18	7.41	7.13
670A RZ 19	19	7.78	7.50
670A RZ 20	20	8.16	7.88
670A RZ 21	21	8.53	8.25
670A RZ 22	22	8.91	8.63
670A RZ 23	23	9.28	9.00
670A RZ 24	24	9.66	9.38
670A RZ 25	25	10.03	9.75
670A RZ 26	26	10.41	10.13
670A RZ 27	27	10.78	10.50
670A RZ 28	28	11.16	10.88
670A RZ 29	29	11.53	11.25
670A RZ 30	30	11.91	11.63

Top Mounted Hardware is .187" Wide
MM = Dim X 25.4

Hardware Options: (Hardware options may affect ratings - consult factory)

KT19	=	Full Quick Connect (0° Flat)	See Page 96
KT20	=	Full Quick Connect (45° Bend)	See Page 96
KT21	=	Full Quick Connect (90° Bend)	See Page 96
ST	=	Full Solder	See Page 97
J 600	=	Line to Line Jumper	See Page 99
600 RJ(S)	=	Multiple Position Jumper	See Page 99
3/4 ST	=	Half Solder	See Page 97
KT25	=	Half Quick Connect (0° Flat)	See Page 96
KT26	=	Half Quick Connect (45° Bend)	See Page 96
KT27	=	Half Quick Connect (90° Bend)	See Page 96
3865	=	Sems Pressure Saddle Screw	See Page 99
Y(L)	=	Feed Thru Solder (.312)	See Page 98
LWW	=	Feed Thru Wire Wrap (.593)	
YSY	=	Feed Thru Solder (.500)	See Page 98
PSB	=	Phil-Slot Brass Screw	

