

ALPHANUMERIC INDEX — CROSS-REFERENCE (Continued)

Industry Part Number	Motorola Direct Replacement	Motorola Similar Replacement	Page Number	Industry Part Number	Motorola Direct Replacement	Motorola Similar Replacement	Page Number
2N6050	2N6050		3-143	2N6188	2N6193		3-158
2N6051	2N6051		3-143	2N6189	2N6193		3-158
2N6051JAN	2N6051JAN		3-143	2N6190	2N6190		3-158
2N6051JTX	2N6051JTX		3-143	2N6191	2N6191		3-158
2N6051JTXV	2N6051JTXV		3-143	2N6192	2N6193		3-158
2N6052	2N6052		3-143	2N6193	2N6193		3-158
2N6052JAN	2N6052JAN		3-143	2N6193JAN	2N6193JAN		3-158
2N6052JTX	2N6052JTX		3-143	2N6193JTX	2N6193JTX		3-158
2N6052JTXV	2N6052JTXV		3-143	2N6193JTXV	2N6193JTXV		3-158
2N6053	2N6053		3-147	2N6211	2N6211		3-161
2N6054	2N6054		3-147	2N6212	2N6212		3-161
2N6055	2N6055		3-147	2N6213	2N6213		3-161
2N6056	2N6056		3-147	2N6226		MJ15016	3-9
2N6057	2N6057		3-143	2N6227		MJ15016	3-9
2N6058	2N6058		3-143	2N6228		MJ15016	3-9
2N6058JAN	2N6058JAN		3-143	2N6229		2N5880	3-123
2N6058JTX	2N6058JTX		3-143	2N6230		MJ15002	3-710
2N6058JTXV	2N6058JTXV		3-143	2N6231		MJ15002	3-710
2N6059	2N6059		3-143	2N6233		2N3584	3-20
2N6059JAN	2N6059JAN		3-143	2N6234		2N3585	3-20
2N6059JTX	2N6059JTX		3-143	2N6235		2N3585	3-20
2N6059JTXV	2N6059JTXV		3-143	2N6242		MJ13015	3-670
2N6077		2N3585	3-20	2N6243		MJ13335	3-700
2N6078		2N3585	3-20	2N6244		MJ13333	3-700
2N6079		2N3585	3-20	2N6245		MJ13335	3-700
2N6098		2N6487	3-207	2N6246		2N5879	3-123
2N6099		2N6487	3-207	2N6247		2N5880	3-123
2N6100		2N6487	3-207	2N6248		MJ15016	3-9
2N6101		2N6488	3-207	2N6249	2N6249		3-164
2N6102		2N6488	3-207	2N6250	2N6250		3-164
2N6103		2N6486	3-207	2N6251	2N6251		3-164
2N6106		2N6107	3-151	2N6253		2N5877	3-120
2N6107	2N6107		3-151	2N6254		2N5878	3-120
2N6108		2N6109	3-151	2N6257		2N5886	3-127
2N6109	2N6109		3-151	2N6258		2N5686	3-112
2N6110		2N6111	3-151	2N6259		2N5631	3-105
2N6111	2N6111		3-151	2N6260		2N3054A	3-2
2N6121	2N6121		3-154	2N6261		2N4233A	3-64
2N6122	2N6122		3-154	2N6262		2N5760	3-116
2N6123	2N6123		3-154	2N6263		2N3584	3-20
2N6124	2N6124		3-154	2N6264		2N3584	3-20
2N6125	2N6125		3-154	2N6270		2N6338	3-188
2N6126		TIP32C	3-1073	2N6271		2N6338	3-188
2N6127		2N6436	3-203	2N6272		2N6338	3-188
2N6128		2N6338	3-188	2N6273		2N6338	3-188
2N6129		TIP41	3-1083	2N6274	2N6274		3-168
2N6130		TIP41A	3-1083	2N6274JAN	2N6274JAN		3-168
2N6131		TIP41B	3-1083	2N6274JTX	2N6274JTX		3-168
2N6132		TIP42C	3-1083	2N6274JTXV	2N6274JTXV		3-168
2N6133		TIP42C	3-1083	2N6275	2N6275		3-168
2N6134		TIP42C	3-1083	2N6276		2N6275	3-168
2N6175		MPS-U10	3-1052	2N6277	2N6277		3-168
2N6176		MPS-U10	3-1052	2N6277JAN	2N6277JAN		3-168
2N6177		MJE340	3-876	2N6277JTX	2N6277JTX		3-168
2N6178		MPS-U06	3-1048	2N6277JTXV	2N6277JTXV		3-168
2N6179		MPS-U05	3-1048	2N6278		2N6274	3-168
2N6180		MPS-U56	3-1062	2N6279		2N6275	3-168
2N6181		MPS-U55	3-1062	2N6280		2N6275	3-168
2N6186	2N6190		3-158	2N6281		2N6277	3-168
2N6187	2N6191		3-158	2N6282	2N6282		3-172

*Consult Motorola if a direct replacement is necessary.