Three-Phase Digital Power Clamp Meter

667C



667C

- Measures Volts, Amps, Watts, VA VARs, KWh, Power factor and Frequency in 3-phase 3-wire, 3-phase 4-wire and single-phase circuits
- Power measurements to 600KW
- Measurements are displayed on a 10,000 count, 4-digit dual LCD display
- 28 measurements may be stored in memory
- Five parameters of a phase measurement may be displayed on the LCD
- Auto ranging and True RMS
- Includes RS232 interface with software
- Amps measurement to 1000Amps with a jaw opening of 2"
- Total 3 phase power measurement

SPECIFICATIONS -

■ AC Amps

Range: 40A, 100A, 400A, 1000A

Best Resolution: 0.1A Accuracy: ±(2% + 5dgt.)

■ AC Volts

Range: 100V, 300V, 600V Best Resolution: 0.1V Accuracy: ±(1.2% + 5dgt.)

■ True power (KW)

Ranges: 4KW, 10KW, 40KW, 600KW

Best Resolution: 0.01KW Accuracy: ±(3.0% + 5dgt.)

■ Apparent power (VA)

Ranges: 4KVA, 10KVA, 40KVA, 600KVA

Best Resolution: 0.01KVA Accuracy: ±(3.0% + 5dgt.)

■ Reactive power (KVAR)

Ranges: 4KVAR, 10KVAR, 40KVAR, 600KVAR

Best Resolution: 0.01KVAR Accuracy: ±(4.0% + 5dgt.)

■ Power Factor (PF)

Range: 0.3 to 1.0 (Capacitive & Inductive)

Resolution: 0.001

Accuracy: ±(0.02% + 2dgt.)

■ Energy (KWh)

Range: 1 to 9999KWh Best Resolution: 0.001KWh Accuracy: ±(2.0% + 5dgt.)

■ Frequency

Range: 20Hz to 1000Hz Best Resolution: 0.1Hz Accuracy: ±0.5%

■ General Specifications

Power: (4) 1.5V AA batteries

Operating Temperature: 0°C to 40°C (32°F to 40°F)

Dimensions: 11.8"(L) x 4.0"(W) x 2"(D)

Weight: 1.1 lbs
Accessories:

Operating manual, Test leads, and Test clamps, (4)1.5V AA batteries, Carrying case, RS232 Cable and Software

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

Protek: