



B8247xx1

Kit contents	Pieces	Values	Datasheets
B82471A1103M000	3	10uH	http://www.epcos.com/inf/30/db/ind_2008/b82471a1.pdf
B82471A1223M000	3	22uH	http://www.epcos.com/inf/30/db/ind_2008/b82471a1.pdf
B82471A1473M000	3	47uH	http://www.epcos.com/inf/30/db/ind_2008/b82471a1.pdf
B82471A1104K000	3	100uH	http://www.epcos.com/inf/30/db/ind_2008/b82471a1.pdf
B82471A1224K000	3	220uH	http://www.epcos.com/inf/30/db/ind_2008/b82471a1.pdf
B82472G4103M000	3	10uH	http://www.epcos.com/inf/30/db/ind_2008/b82472g4.pdf
B82472G4223M000	3	22uH	http://www.epcos.com/inf/30/db/ind_2008/b82472g4.pdf
B82472G4473M000	3	47uH	http://www.epcos.com/inf/30/db/ind_2008/b82472g4.pdf
B82472G4104M000	3	100uH	http://www.epcos.com/inf/30/db/ind_2008/b82472g4.pdf
B82472G4224M000	3	220uH	http://www.epcos.com/inf/30/db/ind_2008/b82472g4.pdf
B82472G6103M000	3	10uH	http://www.epcos.com/inf/30/db/ind_2008/b82472g6.pdf
B82472G6223M000	3	22uH	http://www.epcos.com/inf/30/db/ind_2008/b82472g6.pdf
B82472G6473M000	3	47uH	http://www.epcos.com/inf/30/db/ind_2008/b82472g6.pdf
B82472G6104M000	3	100uH	http://www.epcos.com/inf/30/db/ind_2008/b82472g6.pdf
B82472G6224M000	3	220uH	http://www.epcos.com/inf/30/db/ind_2008/b82472g6.pdf
B82473A1103K000	3	10uH	http://www.epcos.com/inf/30/db/ind_2008/b82473a1.pdf
B82473A1223K000	3	22uH	http://www.epcos.com/inf/30/db/ind_2008/b82473a1.pdf
B82473A1473K000	3	47uH	http://www.epcos.com/inf/30/db/ind_2008/b82473a1.pdf
B82473A1104K000	3	100uH	http://www.epcos.com/inf/30/db/ind_2008/b82473a1.pdf
B82473A1224K000	3	220uH	http://www.epcos.com/inf/30/db/ind_2008/b82473a1.pdf
B82475A1103M000	3	10uH	http://www.epcos.com/inf/30/db/ind_2008/b82475a1.pdf
B82475A1223M000	3	22uH	http://www.epcos.com/inf/30/db/ind_2008/b82475a1.pdf
B82475A1473K000	3	47uH	http://www.epcos.com/inf/30/db/ind_2008/b82475a1.pdf
B82475A1104K000	3	100uH	http://www.epcos.com/inf/30/db/ind_2008/b82475a1.pdf
B82475A1224K000	3	220uH	http://www.epcos.com/inf/30/db/ind_2008/b82475a1.pdf
B82476A1103M000	2	10uH	http://www.epcos.com/inf/30/db/ind_2008/b82476a1.pdf
B82476A1223M000	2	22uH	http://www.epcos.com/inf/30/db/ind_2008/b82476a1.pdf
B82476A1473M000	2	47uH	http://www.epcos.com/inf/30/db/ind_2008/b82476a1.pdf
B82476A1104M000	2	100uH	http://www.epcos.com/inf/30/db/ind_2008/b82476a1.pdf
B82476A1224M000	2	220uH	http://www.epcos.com/inf/30/db/ind_2008/b82476a1.pdf
B82477G2103M000	2	10uH	http://www.epcos.com/inf/30/db/ind_2008/b82477g2.pdf
B82477G2223M000	2	22uH	http://www.epcos.com/inf/30/db/ind_2008/b82477g2.pdf
B82477G2473M000	2	47uH	http://www.epcos.com/inf/30/db/ind_2008/b82477g2.pdf
B82477G2104M000	2	100uH	http://www.epcos.com/inf/30/db/ind_2008/b82477g2.pdf
B82477G2224M000	2	220uH	http://www.epcos.com/inf/30/db/ind_2008/b82477g2.pdf
B82477G4103M000	2	10uH	http://www.epcos.com/inf/30/db/ind_2008/b82477g4.pdf
B82477G4223M000	2	22uH	http://www.epcos.com/inf/30/db/ind_2008/b82477g4.pdf
B82477G4473M000	2	47uH	http://www.epcos.com/inf/30/db/ind_2008/b82477g4.pdf
B82477G4104M000	2	100uH	http://www.epcos.com/inf/30/db/ind_2008/b82477g4.pdf
B82477G4224M000	2	220uH	http://www.epcos.com/inf/30/db/ind_2008/b82477g4.pdf
B82479A1103M000	2	10uH	http://www.epcos.com/inf/30/db/ind_2008/b82479a1.pdf
B82479A1223M000	2	22uH	http://www.epcos.com/inf/30/db/ind_2008/b82479a1.pdf
B82479A1473M000	2	47uH	http://www.epcos.com/inf/30/db/ind_2008/b82479a1.pdf
B82479A1104M000	2	100uH	http://www.epcos.com/inf/30/db/ind_2008/b82479a1.pdf
B82479A1224M000	2	220uH	http://www.epcos.com/inf/30/db/ind_2008/b82479a1.pdf
B82479G1103M000	2	10uH	http://www.epcos.com/inf/30/db/ind_2008/b82479g1.pdf
B82479G1223M000	2	22uH	http://www.epcos.com/inf/30/db/ind_2008/b82479g1.pdf
B82479G1473M000	2	47uH	http://www.epcos.com/inf/30/db/ind_2008/b82479g1.pdf
B82479G1104M000	2	100uH	http://www.epcos.com/inf/30/db/ind_2008/b82479g1.pdf
B82479G1224M000	2	220uH	http://www.epcos.com/inf/30/db/ind_2008/b82479g1.pdf

Kit Quantity: 50