

ALPHANUMERIC INDEX — CROSS-REFERENCE (Continued)

Industry Part Number	Motorola Direct Replacement	Motorola Similar Replacement	Page Number	Industry Part Number	Motorola Direct Replacement	Motorola Similar Replacement	Page Number
BD390-2	BD232	MJE253	3-870	BD439	BD438	MJE3300 MJE3300 MJE3310 MJE3310	3-295
BD390-5		MJE253	3-870	BD440	BD440		3-295
BD390-8		MJE253	3-870	BD441	BD441		3-292
BD410			3-274	BD442	BD442		3-295
BD411		MJE3300	3-906	BD443	BD179		3-268
BD411-1		MJE3300	3-906	BD443A	BD179		3-268
BD411-2		MJE3300	3-906	BD466A			3-906
BD411-5		MJE3300	3-906	BD466B			3-906
BD411-8		MJE3300	3-906	BD477A			3-906
BD412		MJE3300	3-906	BD477B			3-906
BD412-1	BD232	MJE3300	3-906	BD505	MPS-U01	2N6122	3-1040
BD412-2		MJE3300	3-906	BD506	MPS-U51		3-1058
BD412-5		MJE3300	3-906	BD507	MPS-U01		3-1040
BD412-8		MJE3300	3-906	BD508	MPS-U51		3-1058
BD413		MJE3310	3-906	BD509	MPS-U01A		3-1040
BD413-1		MJE3310	3-906	BD510	MPS-U51A		3-1058
BD413-2		MJE3310	3-906	BD515	MPS-U05		3-1048
BD413-5		MJE3310	3-906	BD516	MPS-U55		3-1062
BD413-8		MJE3310	3-906	BD517	MPS-U05		3-1048
BD414		MJE3310	3-906	BD518	MPS-U55		3-1062
BD414-1	BD232	MJE3310	3-906	BD519	MPS-U06	2N6125	3-1048
BD414-2		MJE3310	3-906	BD520	MPS-U56		3-1062
BD414-5		MJE3310	3-906	BD529	MPS-U07		3-1050
BD414-8		MJE3310	3-906	BD530	MPS-U57		3-1064
BD415		MJE181	3-862	BD533			3-154
BD415-1		MJE181	3-862	BD534			3-154
BD415-2		MJE181	3-862	BD535			3-154
BD415-8		MJE181	3-862	BD536			3-154
BD416		MJE171	3-862	BD537			3-154
BD416-1		MJE171	3-862	BD538			3-154
BD416-2	BD232	MJE171	3-862	BD539	BD243	BD787	3-286
BD416-5		MJE171	3-862	BD539A	BD243A		3-286
BD417		MJE182	3-862	BD539B	BD243B		3-286
BD417-1		MJE182	3-862	BD539C	BD243C		3-286
BD417-2		MJE182	3-862	BD540	BD244		3-286
BD417-5		MJE182	3-862	BD540A	BD244A		3-286
BD417-8		MJE182	3-862	BD540B	BD244B		3-286
BD418		MJE172	3-862	BD540C	BD244C		3-286
BD418-1		MJE172	3-862	BD543	BD805		3-316
BD418-2		MJE172	3-862	BD543A	BD807		3-316
BD418-5	BD232	MJE172	3-862	BD543B	BD809	2N6125	3-316
BD418-8		MJE172	3-862	BD544	BD806		3-318
BD419		MJE243	3-870	BD544A	BD808		3-318
BD419-1		MJE243	3-870	BD544B	BD810		3-318
BD419-2		MJE243	3-870	BD546D	BD546D		—
BD419-8		MJE243	3-870	BD561			3-304
BD420		MJE253	3-870	BD575	BD241		3-282
BD420-1		MJE253	3-870	BD576	BD242		3-282
BD420-2		MJE253	3-870	BD577	BD241A		3-282
BD420-5		MJE253	3-870	BD578	BD242A		3-282
BD420-8	BD232	MJE253	3-870	BD579	BD241B	2N6122	3-282
BD424			3-308	BD580	BD242B		3-282
BD429		MJE200	3-866	BD581	BD241C		3-282
BD430		MJE210	3-866	BD582	BD242C		3-282
BD433		BD437	3-292	BD585			3-154
BD434		BD438	3-295	BD586			3-154
BD435		BD437	3-292	BD587			3-154
BD436		BD438	3-295	BD588			3-154
BD437		BD437	3-292	BD589			3-154
BD438		BD438	3-295	BD590			3-154

*Consult Motorola if a direct replacement is necessary.