

# Customer Information Sheet

DRAWING No.: M22520/2-01

SHEET 2 OF 2


IF IN DOUBT - ASK

©

THIRD ANGLE PROJECTION

NOT TO SCALE

ALL DIMENSIONS IN mm



## NOTES:

1. SEE INSTRUCTION SHEET IS-01 FOR INSTRUCTION ON USE OF TOOL.
2. MUST BE USED WITH A POSITIONER:

| POSITIONER | CONTACT PART No. |
|------------|------------------|
| T5747      | M80-0110001      |
| T5747      | M80-0110005      |
| T5747      | M80-0130001      |
| T5747      | M80-0130005      |
| Z80-058    | M80-0550001      |
| Z80-058    | M80-0550005      |
| ZK3609-00  | K3606-06         |
| ZK3609-00  | K3607-T6         |

| JAE           | 3    | 13.12.01 | 6346    |
|---------------|------|----------|---------|
| NAME          | ISS. | DATE     | C/NOTE  |
| APPROVED      |      |          |         |
| CHECKED:      |      |          |         |
| DRAWN:        |      |          | J. KEIR |
| CUSTOMER REF: |      |          |         |
| ASSEMBLY DRG: |      |          |         |

# HARWIN

THIS INFORMATION AND ANY INFORMATION OR DESCRIPTIVE MATTER SET OUT HEREON ARE CONFIDENTIAL AND COPYRIGHT PROPERTY OF THE HARWIN GROUP AND MUST NOT BE DISCLOSED, LOANED, COPIED OR USED FOR MANUFACTURING, TENDERING OR FOR ANY OTHER PURPOSE WITHOUT THEIR WRITTEN PERMISSION.

## TOLERANCES

X. =  $\pm 1\text{mm}$

X.X =  $\pm 0.25\text{mm}$

X.XX =  $\pm 0.10\text{mm}$

X.XXX =  $\pm 0.01\text{mm}$

ANGLES =  $\pm 5^\circ$

UNLESS STATED

## MATERIAL:

FINISH:

S/AREA:

## TITLE:

DATAMATE HAND CRIMP TOOL

DRAWING NUMBER:

**M22520/2-01**

SHT

2

OF

2

HARWIN INC  
U.S.A.  
TEL: (812) 285 0055  
FAX: (812) 285 0056

HARWIN PLC  
U.K.  
TEL: 023 9237 0451  
FAX: 023 9231 4590

HARWIN PTE  
SINGAPORE  
TEL: 65 7794909  
FAX: 65 7793868