



	)#*0+	+%!11)\$)3%+

[illegible][illegible][illegible]

Exploded view diagram of the PC104 Standoff Assembly. The assembly consists of three main components: a 4-40 Screw, a PC104 Standoff, and a 4-40 Hex Nut. The dimensions for the standoff are provided in inches and millimeters:

- 4-40 SCREW
- PC104 STANDOFF
- 4-40 HEX NUT
- Dimensions: .375 [9.5], .600 [15.2], .187 [4.7]

[illegible]

.1 !//+)#!3).-2
42%
