

Technical

APPLICATION Guide

Part Numbering System Indicator Series (PK PF PFD PL PLD ASI)

Part Number Structure

PK – 21 N 31 P Q

Series

PK = Continuous PF = Fast Pulse PL = Slow Pulse

PFD = Dual: Continuous / Fast Pulse

PLD = Dual: Continuous / Slow Pulse

Piezo Element Diameter (mm)Sound Output Level: N = Medium; A = LoudSpecial DesignatorTermination

P = PC Pins W = Wires ER = Screw Terminals

EP = Flat Blade Terminals

RoHS: Q = RoHS Compliant

Part Number Structure

ASI 401 TR Q

Series: ASI = Surface Mount IndicatorUnique IdentifierTermination: TR = Tape-N-ReelRoHS: Q = RoHS CompliantNote:

If there are any questions on the part number, you can download the data sheet for the alarm at:
www.mallory-sonalert.com or you can call for assistance at 317-612-1000.