


SUPPLEMENTARY INFORMATION

FIRST USED

NEXT ASSEMBLY

REVISIONS

REV	DESCRIPTION	DATE	APPROVAL
D	REVISE AND REDRAW	2-22-90	06014 CS
E	TRANSFORMER ASSY WAS 301-1658	7-30-90	06072 RJM
F	REVISE AND REDRAW BS & CVR MKG -02, -0N	3-19-91	16056 RJM
G	ADD -OP TO TABULATION	10-22-91	1025 JL
H	REVISE BOBBIN VIEW	5-15-95	56035 SK



COVER MARKING
(SEE TABULATION)

PWB ASSEMBLY
080-2751
(NOT ALL COMPONENTS
SHOWN FOR CLARITY.)

INSULATOR PAPER
200-4279

HOTMELT

SCREW
681-5167-100

WASHERS
683-1001
(QTY. 2)

TRANSFORMER ASSY
301-2323

SEE DETAIL "A"
FOR FUSE HOOK-UP.

BASE MARKING
(SEE TABULATION)

BLK (-)

RED (+)

INSULATOR PAPER
200-4286
(INSERT BETWEEN
XFMR & HEATSINK)

SEE DETAIL "A"
FOR WIRE HOOK-UP.

NYLON SPACER
683-1392
(QTY. 2)

DETAIL "B"

AC PRONGS
200-4131-002
(QTY. 2)

BLACK
RED
FROM PWB
ASSEMBLY

UNIT PART NUMBER	REV	BASE MARKING	COVER MARKING
3VA-06030-00	Q	150-4243	150-4273
3VA-06030-02	P	150-4416	150-4415
3VA-06030-07	K	150-4252	150-4273
3VA-06030-0N	E	150-4414	150-4415
3VA-06030-0P	B	150-4575	150-4583

BATTERY
CHARGER
FINAL
ASS'Y



AULT INCORPORATED
MINNEAPOLIS, MINNESOTA

SIZE DRAWING NO.

3VA-06030-0X

REV

H

ISS

1

TOLERANCES UNLESS NOTED OTHERWISE	DRAWN BY	R. MOE	4-6-88
X ± .020	DRAFTING		
XX ± .010	MATL & FIN		
XXX ± .005	DESIGNER		
	DESIGN		
	APPROVED		

1. APPLY RTV (687-1262) ON POTS
PRIOR TO ADJUSTMENT.

SHEET 1 OF 1