

Exploded view diagram of a mechanical assembly. The diagram shows various components numbered 1 through 60, including a central motor unit, mounting brackets, screws, and a terminal block. Key dimensions and labels include:

- Top left: 1.52 [± 0.060]
- Top right: 6.35 ± 0.5 [$\pm 0.250 \pm 0.020$]
- Top right: REF 8, REF 34
- Top right: TERMINAL SUPPORT LOCATION
- Bottom left: * WARNING ON INSTALLATION, SET WIRE DISC TO LARGEST WIRE SIZE

-	-	-	-	-	-	-	-	-	83
-	-	-	-	-	-	-	-	-	82
-	-	-	-	-	-	-	-	-	81
-	-	-	-	-	-	-	-	-	80
-	-	-	-	-	-	-	-	-	79
-	-	-	-	-	-	-	-	-	78
-	-	-	-	-	-	-	-	-	77
-	-	-	-	-	-	-	-	-	76
-	-	-	-	-	-	-	-	-	75
-	-	-	-	-	-	-	-	-	74
-77	-76	-72	-71	-6	-2	-1	PART NO	DESCRIPTION	ITEM NO

[illegible]