







REV.

B

## CERAMIC TRIMMER CAPACITOR



## NON-STD HOLE PATTERN WITH / WITHOUT UNIT



|       |          |      |                |      |        |
|-------|----------|------|----------------|------|--------|
| B     | 3/6/13   | RJV  | RJV 3/6/13 MAI |      | 001125 |
| A     | 10/19/11 | RJV  | -              | -    | 001007 |
| LEVEL | DATE     | DRN. | CHK.           | APP. | ECN    |

## REVISIONS

|                  |                  |                  |                           |
|------------------|------------------|------------------|---------------------------|
| DRN.<br>RJV      | CHK.<br>RJV      | APP.<br>MAI      | SCALE<br>4" = 1"          |
| DATE<br>10/19/11 | DATE<br>10/19/11 | DATE<br>10/20/11 | .XX ± .015<br>.XXX ± .005 |



## JOHANSON MANUFACTURING CORPORATION

ROCKAWAY VALLEY ROAD, BOONTON, N.J. 07005 (973)334-2676 FAX (973)334-2954  
ELECTRONIC ACCURACY THROUGH MECHANICAL PRECISION

PROPRIETARY INFORMATION CONTAINED NOT TO BE USED WITHOUT JOHANSON MANUFACTURING CORPORATION APPROVAL